

07/10/2026 15:05:18 by Operator-1068

Security Classification: OFFICIAL - SENSITIVE - PERSONAL DATA. Do not disclose this report outside the LFB. Refer any request for a copy to Information Management (ext 30422)

Incident Log - **Inc No.**

Incident	Inc No.	Taken by SW2	at 16:55:30	Stn E35	Status C
----------	----------------	---------------------	--------------------	----------------	-----------------

Call 16:55:30	Address 16:56:25	Created 16:56:25
Assigned 16:56:25	Alerted 16:56:25	
Mobile 16:57:46	On Scene 16:59:09	Stop 20:00:47

Original Type A1
Additional Types 4PF
6PF
A1F
FSG
PR
Revised Type F
Incident Tags 30
4PF
6PF
A1
A1_DEFAULT
A1F
FSG
PR
SM1

Repeat Calls 9
Incidents 000504-01012023
000505-01012023
000506-01012023
000507-01012023
000508-01012023
000511-01012023
000514-01012023
000515-01012023
000524-01012023

Caller	Caller No.	Call Source 999
Address	No.	

Summary	s.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE ** INCIDENT TO BE LEFT OPEN AS SA4 WILL BE RE-ATTENDING WITH FIT ON 03/01/23 **
---------	--

Officer In Charge Unknown
Stop Message 01/01/2023 20:00:48
CU4 FROM SC S.40 STOP A SHOP AND DWELLINGS OF 3 FLOORS 6M X 20M FIVE ROOMED HMO ON 1ST AND 2ND FLOOR 50 PER CENT OF FIRST FLOOR DXF 50 PER CENT OF 2ND FLOOR DXF 50 PER CENT OF STAIRCASE BETWEEN GROUND AND 2ND FLOOR DXF s.41
s.41
s.41
s.41
s.41
s.41
S.40 S
2 JETS HR 10 BA STAGE
ONE ENTRY CONTROL TL TIC MDT APAF SAAC TMO

Appliances

Csign	Stn	St	OIC	Ri	Plus	Assign	Alerted	Mobile	On Sc	Avail	Return
E351	E35	1		0	Y	16:56:25	16:56:25	16:57:59	16:59:09	19:17:06	19:17:06
E341	E34	1		0	Y	16:56:25	16:56:25	16:57:46	17:01:37	19:19:53	19:19:53
E381	E38	1		0	Y	16:58:25	16:58:25	16:59:07	17:03:48	19:09:28	19:09:28
OK10	F90	P		0	Y	16:58:25	16:58:25			17:04:59	17:04:59
CU4	E34	1		0	Y	16:58:25	16:58:25	16:59:40	17:05:53	20:09:56	20:09:56
E371	E37	6	S.40	5		16:59:23	16:59:23	17:00:13	17:04:02	19:16:27	19:16:27
OK13	F90	P		0		17:04:37	17:04:37	17:05:15	17:13:43	22:45:56	22:45:56
E354	E35	1		0		17:08:04	17:08:04	17:09:04	18:16:07	19:08:33	19:08:33
E221	E22	1		0		17:10:05	17:10:05	17:11:51	17:20:04	19:05:00	19:05:00
CU5	E31	1		0		17:17:39	17:17:39	17:20:04	17:34:38	19:40:58	19:40:58
H241	H24	1		0		17:17:39	17:17:39	17:18:37	17:24:45	19:11:35	19:11:35
F331	F33	5	SUBO S.40	5		17:54:29	17:54:29			17:55:08	17:55:08
E361	E36	1		0		17:54:29	17:54:29			17:56:42	17:56:42
CU3	F45	1		0		17:54:29	17:54:29	17:56:43		17:59:30	17:59:30
F331	F33	1		0		17:56:57	17:56:57			17:57:46	17:57:46
E361	E36	1	SUBO	0		17:56:57	17:56:57	17:57:08	19:05:17	20:51:56	20:51:56
F331	F33	6	SUBO S.40	5		17:57:55	17:57:55	17:59:03	18:03:07	20:01:15	20:01:15
OK15	F90	7		0		18:01:13	18:01:13	18:02:03	18:18:24	20:29:09	20:29:09
E232	E23	1		0		20:14:25	20:14:25	20:17:01	20:39:33	00:09:13	00:09:13
H242	H24	1		0		23:24:26	23:24:26	23:47:12	23:59:22	01:15:47	01:15:47
OK16	F90	P		0		10:24:27	10:24:27	10:25:09	11:24:39	17:03:14	17:03:14
OK14	F90	P		0		10:24:37	10:24:37	10:25:04	11:24:35	17:02:29	17:02:29
E351	E35	1		0		12:09:58	12:09:58	12:11:02	12:11:25	12:41:16	12:41:16
OK16	F90	P		0		09:42:29	09:42:29		10:14:10	16:52:45	16:52:45
OK15	F90	P		0		09:42:42	09:42:42		10:08:08	16:20:32	16:20:32
E351	E35	7	SUBO S.40	5		11:31:52	11:31:52	11:33:25	11:42:08	11:47:36	11:47:36
OK13	F90	P		0		14:08:03	14:08:03		14:08:07	17:33:50	17:33:50
OK13	F90	P		0	Y	07:49:02	07:49:02	08:26:54		20:38:44	20:38:44
E351	E35	1		0		08:40:12	08:40:12	08:42:27	08:45:26	08:48:43	08:48:43
OK15	F90	P		0		12:14:09	12:14:09	12:14:37	12:37:27	18:04:38	18:04:38
Callsign	Activation			Response			At Scene		Committed		
E351	00:01:34			00:02:44			02:17:57		02:20:41		
E341	00:01:21			00:05:12			02:18:16		02:23:28		
E381	00:02:42			00:07:23			02:05:40		02:11:03		
OK10									00:06:34		
CU4	00:03:15			00:09:28			03:04:03		03:11:31		
E371	00:03:48			00:07:37			02:12:25		02:17:04		
OK13	00:08:50			00:17:18			05:32:13		05:41:19		
E354	00:12:39			01:19:42			00:52:26		02:00:29		
E221	00:15:26			00:23:39			01:44:56		01:54:55		
CU5	00:23:39			00:38:13			02:06:20		02:23:19		
H241	00:22:12			00:28:20			01:46:50		01:53:56		
F331									00:00:39		
E361									00:02:13		
CU3	01:00:18								00:05:01		
F331									00:00:49		
E361	01:00:43			02:08:52			01:46:39		02:54:59		
F331	01:02:38			01:06:42			01:58:08		02:03:20		
OK15	01:05:38			01:21:59			02:10:45		02:27:56		
E232	03:20:36			03:43:08			03:29:40		03:54:48		
H242	06:50:47			07:02:57			01:16:25		01:51:21		
OK16	17:28:44			18:28:14			05:38:35		06:38:47		
OK14	17:28:39			18:28:10			05:37:54		06:37:52		
E351	19:14:37			19:15:00			00:29:51		00:31:18		
OK16				41:17:45			06:38:35		07:10:16		
OK15				41:11:43			06:12:24		06:37:50		
E351	42:37:00			42:45:43			00:05:28		00:15:44		

OK13		45:11:42	03:25:43	03:25:47
OK13	63:30:29			12:49:42
E351	63:46:02	63:49:01	00:03:17	00:08:31
OK15	67:18:12	67:41:02	05:27:11	05:50:29

Officers

Csign	Name	Assign	Alerted	Mobile	On Sc	Avail	Return
F121							
F25S	S.40, S.40	16:58:25	16:58:25	17:01:57	17:14:10	20:30:31	20:30:31
F63							
F110							
A37S	S.40	17:03:28	17:06:52	17:07:05	17:28:22	20:08:11	20:08:11
F121	S.40	17:06:12	17:06:12	17:07:09	17:28:23	21:23:58	21:23:58
G37S	S.40	17:07:49	17:07:49	17:15:48	17:28:25	21:20:38	21:20:38
G24S	S.40	17:17:39	17:17:39	17:20:01	17:42:43	18:29:01	18:29:01
F110	S.40	17:28:36	17:28:36	17:28:56	17:39:27	19:49:29	19:49:29
E1							
OF64	S.40	17:54:29	17:54:29			17:59:32	17:59:32
F63							
BC02							
SA3							
H26S							
F63	S.40	18:15:02	18:15:02	18:15:31	18:36:59	20:56:57	20:56:57
PR4							
SA4	S.40	10:30:15	10:30:15	10:37:24	11:10:48	17:16:55	17:16:55
SA4	S.40	10:41:57	10:41:57		10:42:10	16:19:03	16:19:03
SA4	S.40	08:39:06	08:39:06	08:39:14	08:39:19	17:10:13	17:10:13

Callsign	Activation	Response	At Scene	Committed
F121				
F25S	00:05:32	00:17:45	03:16:21	03:32:06
F63				
F110				
A37S	00:10:40	00:31:57	02:39:49	03:04:43
F121	00:10:44	00:31:58	03:55:35	04:17:46
G37S	00:19:23	00:32:00	03:52:13	04:12:49
G24S	00:23:36	00:46:18	00:46:18	01:11:22
F110	00:32:31	00:43:02	02:10:02	02:20:53
E1				
OF64				00:05:03
F63				
BC02				
SA3				
H26S				
F63	01:19:06	01:40:34	02:19:58	02:41:55
PR4				
SA4	17:40:59	18:14:23	06:06:07	06:46:40
SA4		41:45:45	05:36:53	05:37:06
SA4	63:42:49	63:42:54	08:30:54	08:31:07

Additional Data

Name	Data
Borough	Southwark
Command Areas	South East
Electricity Provider	UKPN
OtherAgencyCallRef	TFL REF 311 TWA 31920995 / TWA NEW REFERENCE 31920998 / UKPN REF CALL619350J
Water Company	Thames

Narrative			
Time	Op	Csign	Message
01/01/2023			
16:55:30	SW2		Call Collection New incident key pressed
16:55:31	SW2		Call Collection ANI/ALI processed: Mobile CLI [Caller No.], (x [533807, 1200],y [178323, 1200], angle 90)
16:55:45	SW2		Call Collection ANI/ALI processed: Mobile CLI [Caller No.], (x [533478, 10],y [178460, 10], angle 0)
16:55:48	SW2		Call Collection Gazetteer searched
16:55:48	SW2		Call Collection Gazetteer search ended
16:55:55	SW2		Call Collection Address selected (not replaced): [Address], [No.] OLD KENT ROAD , LONDON , SE1 5LU (200003372226) (533485,178472)
16:56:18	SW2		Call Collection Form "Fire Additional Types" added
16:56:19	SW2		Call Collection Map book ref: 7J/231
16:56:24	SW2		Call Collection Incident created
16:56:24	SW2		Call Collection Position ID: WMEROPC014
16:56:24	SW2		Tag A1 added
16:56:24	SW2		Tag 30 added
16:56:24	SW2		Tag A1_DEFAULT added
16:56:25	SYS		R/C set to 35
16:56:25	SW2		Custom Form Attached Type: Call Collection Comments: None
16:56:25	SW2		Custom Form Attached Type: Fire Additional Types Comments: None
16:56:25	SW2		Call Collection Address selected
16:56:25	SW2		Call Collection Map Ref: 7J/231
16:56:25	SW2		Mobilisation Turnout Methods Offered E351 : [W] [M] V E341 : [W] [M] V
16:56:25	SW2		Status changed from E - Existing to P - Pending
16:56:25	SYS		Action Prompt [Inc No.] -01012023(M) under resourced displayed to All
16:56:25	SW2	E351	Officer In Charge changed from to [S.41] STNO
16:56:25	SW2	E351	Riders changed from 0 to 5
16:56:25	SW2	E351	Status changed from 1 - At Station to R - Committed To Incident
16:56:25	SW2	E351	Assigned to Incident [Inc No.] -01012023
16:56:25	SW2	E351	Role changed from AERIAL SUPPORT PUMP to PUMPING APPLIANCE,LONDON PUMPING APPLIANCE,135 LADDER,SUB OR STN OFFICER
16:56:25	SW2	E341	Officer In Charge changed from to 51655P SUBO

16:56:25	SW2	E341	Riders changed from 0 to 5
16:56:25	SW2	E341	Status changed from 1 - At Station to R - Committed To Incident
16:56:25	SW2	E341	Assigned to Incident Inc No. -01012023
16:56:25	SW2	E341	Role changed from PUMPING APPLIANCE to PUMPING APPLIANCE,LONDON PUMPING APPLIANCE
16:56:25	SW2		Mobilisation SW2 Turnout E351 (W),E351 (M),E341 (W),E341 (M) to Inc No. -01012023
16:56:25	SW2	E35	Mobilisation Initial - Turnout Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Creation Date/Time: 01/01/2023 16:56:24 Incident Type: A1 Incident Details: FIRE IN FLAT S.41 S.41 FLOOR Incident Address: , No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: E351 Resource Attribute Codes: PA Resource Attribute Codes: LFBPA Resource Attribute Codes: 135 Resource Attribute Codes: SUBSTNO END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: Resource Call Sign: E341 Resource Attribute Codes: PA Resource Attribute Codes: LFBPA END Group - Resources Being Assigned From Other Location Caller Phone Number: Caller No.
16:56:25	SW2	E34	Mobilisation Initial - Turnout Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Creation Date/Time: 01/01/2023 16:56:24 Incident Type: A1 Incident Details: FIRE IN FLAT S.41 S.41 FLOOR Incident Address: , No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: E341 Resource Attribute Codes: PA Resource Attribute Codes: LFBPA END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40

			START Group - Resources Being Assigned From Other Location: Resource Call Sign: E351 Resource Attribute Codes: PA Resource Attribute Codes: LFBPA Resource Attribute Codes: 135 Resource Attribute Codes: SUBSTNO END Group - Resources Being Assigned From Other Location Caller Phone Number: Caller No.
16:56:25	SW2		Mobilisation Required response met
16:56:25	SW2		Mobilisation Required response met
16:56:25	SYS		Action Prompt Inc No. -01012023(M) under resourced displayed to All
16:56:26	SYS		Incident turnout to E35 for E351 completed [19786]
16:56:26	SYS		Incident turnout to E34 for E341 completed [19788]
16:56:28	SYS		Incident turnout to E341 for E341 completed [19792]
16:56:29	SYS		Incident turnout to E351 for E351 completed [19790]
16:56:29	SW2		Custom Form Attached Type: Call Completion Comments: None
16:56:29	SW2		Custom Form Attached Type: Fire Additional Types (#1) Comments: None
16:56:29	SW2		Call Collection Call Collection Completed
16:56:36	SYS		Incident turnout to E34 for E341 crew acknowledgement received [19788]
16:57:04	SW2	E351	Additional Type PR added
16:57:04	SW2		Action Action Plan 2772 Activated
16:57:04	SW2		Tag PR added
16:57:05	SYS		Action Prompt Inc No. -01012023(M) under resourced displayed to All
16:57:26	SW2		Details changed from FIRE IN FLAT S.41 S.41 FLOOR to FIRE IN FLAT S.41 PERSONS REPORTED BY CONTROL S.41 FLOOR
16:57:26	SW2		Incident details update sent to E351,E341
16:57:30	SYS		Incident turnout to E351 for E351 completed [19795]
16:57:30	SYS		Incident turnout to E341 for E341 completed [19797]
16:57:31	SYS		Incident turnout to E35 for E351 no crew acknowledgement received [19786]
16:57:31	SYS		Incident turnout to E351 for E351 no crew acknowledgement received [19790]
16:57:31	SYS		Incident turnout to E341 for E341 no crew acknowledgement received [19792]
16:57:33	SYS	E351	Action Prompt E351 (E35) not booked mobile to incident displayed to All
16:57:33	SYS	E341	Action Prompt E341 (E34) not booked mobile to incident displayed to All
16:57:45	SYS		Status changed from P - Pending to M - Mobile Incident

16:57:45	SYS	E341	Status changed from R - Committed To Incident to 2 - Proceeding to incident
16:57:45	SYS	E341	Officer In Charge changed from S.40 SUBO to -
16:57:47	SW2		Action ALERT SPVR TO COMPLETE THEIR PART OF ACTION PLAN Completed VB
16:57:59	SYS	E351	Status changed from R - Committed To Incident to 2 - Proceeding to incident
16:57:59	SYS	E351	Officer In Charge changed from S.40 STNO to -
16:58:21	LOB	F121	Informed of incident Inc No. -01012023
16:58:21	LOB		Mobilisation
16:58:21	LOB		Inform F121 (P) of Inc No. -01012023
16:58:21	LOB		User Comment
			FIRE IN FLAT S.41 PERSONS REPORTED BY CONTROL S.41 FLOOR
			Turning out with message - F121 PAGED AS FSO
16:58:22	SYS		Inform to F121 for F121 completed [19800]
16:58:24	MPE		Mobilisation Turnout Methods Offered
			E381 : [W] [M] V
			OK10 : [W] [P] V
			CU4 : [W] [M] V
			F25S : [P] V
16:58:24	MPE	E381	Officer In Charge changed from to S.40 SUBO
16:58:24	MPE	E381	Riders changed from 0 to 5
16:58:24	MPE	E381	Status changed from 1 - At Station to R - Committed To Incident
16:58:24	MPE	E381	Assigned to Incident Inc No. -01012023
16:58:24	MPE	OK10	Status changed from P - Available by pager to R - Committed To Incident
16:58:24	MPE	OK10	Assigned to Incident Inc No. -01012023
16:58:24	MPE	CU4	Officer In Charge changed from to S.40 SUBO
16:58:24	MPE	CU4	Riders changed from 0 to 3
16:58:24	MPE	CU4	Status changed from 1 - At Station to R - Committed To Incident
16:58:24	MPE	CU4	Assigned to Incident Inc No. -01012023
16:58:24	MPE	F25S	Status changed from P - Available by Paging to R - Committed
16:58:24	MPE	F25S	Role changed from OD2 to STATION COMMANDER
16:58:24	MPE	F25S	Assigned to Incident Inc No. -01012023
16:58:24	MPE		Mobilisation MPE
			Turnout E381 (W),E381 (M),OK10 (W),OK10 (P),CU4 (W),CU4 (M) to Inc No. -01012023
16:58:24	MPE	E38	Mobilisation
			Initial - Turnout
			Incident Number: Inc No. -01012023
			Incident Call Date/Time: 01/01/2023 16:55:30
			Incident Creation Date/Time: 01/01/2023 16:56:24
			Incident Type: A1
			Incident Type: PR
			Incident Details: FIRE IN FLAT S.41 PERSONS REPORTED BY CONTROL S.41

			FLOOR Incident Address: [REDACTED] [REDACTED], No. [REDACTED] OLD KENT ROAD, LONDON, SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: E381 Resource Attribute Codes: PA END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 [REDACTED] START Group - Resources Being Assigned From Other Location: Resource Call Sign: OK10 Resource Attribute Codes: FIU Resource Call Sign: CU4 Resource Attribute Codes: CU Resource Call Sign: F25S Resource Attribute Codes: SC END Group - Resources Being Assigned From Other Location Caller Phone Number: [REDACTED] Caller No. Mobilisation Initial - Turnout Incident Number: [REDACTED] Inc No. [REDACTED]-01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Creation Date/Time: 01/01/2023 16:56:24 Incident Type: A1 Incident Type: PR Incident Details: FIRE IN FLAT S.41 [REDACTED] PERSONS REPORTED BY CONTROL S.41 [REDACTED] FLOOR Incident Address: [REDACTED] [REDACTED], No. [REDACTED] OLD KENT ROAD, LONDON, SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: OK10 Resource Attribute Codes: FIU END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 [REDACTED] START Group - Resources Being Assigned From Other Location: Resource Call Sign: E381 Resource Attribute Codes: PA Resource Call Sign: CU4 Resource Attribute Codes: CU Resource Call Sign: F25S Resource Attribute Codes: SC END Group - Resources Being Assigned From Other Location Caller Phone Number: [REDACTED] Caller No. Mobilisation Initial - Turnout Incident Number: [REDACTED] Inc No. [REDACTED]-01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Creation Date/Time: 01/01/2023 16:56:24 Incident Type: A1
16:58:24	MPE	F90	
16:58:24	MPE	E34	

			Incident Type: PR
			Incident Details: FIRE IN FLAT S.41
			PERSONS REPORTED BY CONTROL S.41
			FLOOR
			Incident Address: , No.
			OLD KENT ROAD, LONDON, SE1 5LU
			START Group - Resources Being Assigned
			From This Location:
			Resource Call Sign: CU4
			Resource Attribute Codes: CU
			END Group - Resources Being Assigned From
			This Location
			Incident Map Book Reference: 7J/231
			Incident Station Ground: E35
			S.40
			START Group - Resources Being Assigned
			From Other Location:
			Resource Call Sign: E381
			Resource Attribute Codes: PA
			Resource Call Sign: OK10
			Resource Attribute Codes: FIU
			Resource Call Sign: F25S
			Resource Attribute Codes: SC
			END Group - Resources Being Assigned From
			Other Location
			Caller Phone Number: Caller No.
16:58:24	MPE		Mobilisation MPE
16:58:25	MPE		Turnout F25S (P) to Inc No. -01012023
			Mobilisation
			Required response met
16:58:25	SYS		Incident turnout to E34 for CU4 completed
			[19807]
16:58:25	SYS		Incident turnout to F90 for OK10 completed
			[19805]
16:58:25	MPE		Mobilisation
			Required response met
16:58:26	SYS		Incident turnout to E38 for E381 completed
			[19803]
16:58:27	SYS		Incident turnout to F25S for F25S completed
			[19813]
16:58:28	SYS		Incident turnout to E381 for E381 completed
			[19809]
16:58:29	SYS		Incident turnout to CU4 for CU4 completed
			[19812]
16:58:29	LOB		Action INFORM FS OFFICER IF NOT ALREADY
			ATTENDING Completed
			F121 PAGED AS FSO
16:58:35	SYS		Incident turnout to E34 for CU4 crew
			acknowledgement received [19807]
16:58:37	LOB		Agency
			F121 PAGED AS FSO
16:58:38	SYS		Incident turnout to F90 for OK10 crew
			acknowledgement received [19805]
16:58:43	LS1		000504-01012023 identified as a repeat of this
			incident
16:58:59	KH		000505-01012023 identified as a repeat of this
			incident
16:59:00	VB1	F63	Informed of incident Inc No. -01012023
16:59:00	VB1		Mobilisation
			Inform F63 (P) of Inc No. -01012023
16:59:00	VB1		User Comment
			FIRE IN FLAT S.41 PERSONS REPORTED BY
			CONTROL S.41 FLOOR

16:59:01	SYS		Turning out with message - paged to inform Inform to F63 for F63 completed [19815]
16:59:05	SYS		Incident turnout to E381 for E381 crew acknowledgement received [19809]
16:59:07	SYS	E381	Status changed from R - Committed To Incident to 2 - Proceeding to incident
16:59:07	SYS	E381	Officer In Charge changed from S.40 SUBO to -
16:59:09	SYS		Status changed from M - Mobile Incident to I - In Attendance
16:59:09	SYS	E351	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
16:59:16	MPE		Details changed from FIRE IN FLAT S.41 PERSONS REPORTED BY CONTROL S.41 FLOOR to FIRE IN FLAT S.41 - MULTIPLE CALLS ADDITIONAL * * PERSONS REPORTED BY CONTROL S.41 FLOOR * *
16:59:16	MPE		Incident details update sent to E341,E381,CU4
16:59:19	SYS		Incident turnout to E341 for E341 completed [19818]
16:59:22	MC		000506-01012023 identified as a repeat of this incident
16:59:22	MC		Tag SM1 added
16:59:22	MC		Incident Priority changed from M to H
16:59:22	SYS		Incident turnout to CU4 for CU4 completed [19824]
16:59:22	MPE		Mobilisation Turnout Methods Offered E371 : [M] V
16:59:22	MPE	E371	Status changed from 6 - Immediately available by radio to R - Committed To Incident
16:59:22	MPE	E371	Assigned to Incident Inc No. -01012023
16:59:22	MPE		Mobilisation MPE Turnout E371 (M) to Inc No. -01012023
16:59:22	MPE		Mobilisation Required response met
16:59:22	MPE		Mobilisation Required response met
16:59:23	SYS		Incident turnout to E381 for E381 completed [19821]
16:59:25	VB1		Action SUPERVISOR INFORM - ORT Completed F63 PAGED
16:59:26	SYS		Incident turnout to E371 for E371 completed [19828]
16:59:27	SYS		Incident turnout to OK10 for OK10 completed [19810]
16:59:30	SYS		Incident turnout to E38 for E381 no crew acknowledgement received [19803]
16:59:30	SYS		Incident turnout to CU4 for CU4 no crew acknowledgement received [19812]
16:59:33	SYS	CU4	Action Prompt CU4 (E34) not booked mobile to incident displayed to All
16:59:33	SYS	OK10	Action Prompt OK10 (F90) not booked mobile to incident displayed to All
16:59:40	SYS	CU4	Status changed from R - Committed To Incident to 2 - Proceeding to incident
16:59:40	SYS	CU4	Officer In Charge changed from S.40 SUBO to -

16:59:55	SB1		000507-01012023 identified as a repeat of this incident
16:59:58	SYS		Incident turnout to E371 for E371 crew acknowledgement received [19828]
17:00:04	EK		000508-01012023 identified as a repeat of this incident
17:00:12	SYS	E371	Status changed from R - Committed To Incident to 2 - Proceeding to incident
17:00:21	SW2		Action ORDER AMBULANCE Completed ORDERED AMB LAS REF 4561
17:00:23	MPE		Key RT5/E - E351 - MULTIPLE CALLS RECEIVED TO INCIDENT AND PERSONS REPORTED BY CONTROL - E371 E381 CU4 AND SC ORDERED ADDITIONALLY
17:01:02	MPE	F121	Informed of incident Inc No. -01012023
17:01:02	MPE		Mobilisation Inform F121 (P) of Inc No. -01012023
17:01:02	MPE		User Comment FIRE IN FLAT S.41 - MULTIPLE CALLS ADDITIONAL * * PERSONS REPORTED BY CONTROL S.41 FLOOR * *
			Turning out with message - F121 INFORMED AS GC MONITORING
17:01:03	SYS		Inform to F121 for F121 completed [19829]
17:01:14	MPE		Agency F121 INFORMED AS GC MONITORING
17:01:37	SYS	E341	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:01:54	TS3		Make Up IUP E351 FROM SUB S.41 MAKE PUMPS FOUR PERSONS REPORTED REQ URGENT ATTENDANCE OF POLICE FOR TRAFFIC CONTROL
17:01:55	LOB		Action INFORM POLICE Completed CAD6062
17:01:56	SW2	F25S	Status changed from R - Committed to 2 - Proceeding to incident
17:02:10	LOB		Service Request Service Request Updated from IUP E351 FROM SUB S.41 MAKE PUMPS FOUR PERSONS REPORTED REQ URGENT ATTENDANCE OF POLICE FOR TRAFFIC CONTROL , to LO - IUP E351 FROM SUB S.41 MAKE PUMPS FOUR PERSONS REPORTED REQ URGENT ATTENDANCE OF POLICE FOR TRAFFIC CONTROL
17:02:10	LOB		Service Request Service Request InProgress: LO - IUP E351 FROM SUB S.41 MAKE PUMPS FOUR PERSONS REPORTED REQ URGENT ATTENDANCE OF POLICE FOR TRAFFIC CONTROL
17:02:19	LOB	E351	Additional Type 4PF added
17:02:19	LOB		Action Action Plan 2726 Activated
17:02:19	LOB		Tag 4PF added
17:02:31	LOB		Details changed from FIRE IN FLAT S.41 - MULTIPLE CALLS ADDITIONAL

			** PERSONS REPORTED BY CONTROL S.41 FLOOR ** to FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL ** PERSONS REPORTED BY CONTROL S.41 FLOOR **
17:02:31	LOB		Incident details update sent to E381,CU4,E371
17:02:34	TS3		Service Request Service Request Completed: RT5/E - E351 - MULTIPLE CALLS RECEIVED TO INCIDENT AND PERSONS REPORTED BY CONTROL - E371 E381 CU4 AND SC ORDERED ADDITIONALLY
17:02:34	SYS		Incident turnout to E381 for E381 completed [19850]
17:02:35	SYS		Incident turnout to CU4 for CU4 completed [19853]
17:02:47	SYS		Incident turnout to E371 for E371 completed [19856]
17:02:57	LOB		Action ALERT SPVR TO COMPLETE THEIR PART OF ACTION PLAN Completed VB
17:03:11	KH		000511-01012023 identified as a repeat of this incident
17:03:12	MPE	F110	Informed of incident Inc No. -01012023
17:03:12	MPE		Mobilisation Inform F110 (P) of Inc No. -01012023
17:03:12	MPE		User Comment FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL ** PERSONS REPORTED BY CONTROL S.41 FLOOR **
			Turning out with message - F110 INFORMED AS GC MONITORING
17:03:12	SYS		Inform to F110 for F110 completed [19861]
17:03:27	LOB	A37S	Informed of incident Inc No. -01012023
17:03:27	LOB		Mobilisation Inform A37S (P) of Inc No. -01012023
17:03:27	LOB		User Comment FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL ** PERSONS REPORTED BY CONTROL S.41 FLOOR **
			Turning out with message - A37S PAGED AS PR
17:03:28	EK	F121	User Comment Acknowledged receipt of incident Inc No. -01012023
17:03:28	SYS		Inform to A37S for A37S completed [19862]
17:03:29	EK	F121	F121 not proceeding to incident
17:03:36	LOB		Action INFORM OFFICER WITH ATTRIBUTE OF PR Completed A37S PAGED AS PR
17:03:39	MPE		Key F110 INFORMED AS GC MONITORING IN PLACE OF F121 WHO IS FSO
17:03:43	LOB		Agency A37S PAGED AS PR
17:03:47	SYS	E381	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident

17:03:49	EK		Agency F121 RESPONDED TO PAGING AND MONITORING AS GC
17:04:01	SYS	E371	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:04:04	LOB		Action INFORM FS OFFICER IF NOT ALREADY ATTENDING Completed DONE
17:04:09	LOB		Action INFORM POLICE Completed DONE
17:04:13	LOB		Action ACTION MP4 Completed NOTED
17:04:23	LOB		Action SUPERVISOR INFORM - ORT Completed AS ABOVE
17:04:33	LOB		Action SUPERVISOR INFORM – CML FOR 4PG FIRES Completed CML AWARE
17:04:37	MPE		Mobilisation Turnout Methods Offered OK13 : [W] [M] V
17:04:37	MPE	OK13	Status changed from P - Available by pager to R - Committed To Incident
17:04:37	MPE	OK13	Assigned to Incident Inc No. -01012023
17:04:37	MPE	OK13	Role changed from FIRE INVESTIGATION UNIT to FIU
17:04:37	MPE		Mobilisation MPE Turnout OK13 (W),OK13 (M) to Inc No. -01012023
17:04:37	MPE	F90	Mobilisation Make Up - Makeup

Incident Number: **Inc No.** -01012023
 Incident Call Date/Time: 01/01/2023 16:55:30
 Incident Type: A1
 Incident Type: PR
 Incident Type: 4PF
 Incident Details: FOUR PUMP FIRE - MULTIPLE
 CALLS ADDITIONAL
 * * PERSONS REPORTED BY CONTROL **S.41**
 FLOOR * *
 Incident Address: **No.**
 OLD KENT ROAD,LONDON,SE1 5LU
 START Group - Resources Being Assigned
 From This Location:
 Resource Call Sign: OK13
 Resource Attribute Codes: FIU
 END Group - Resources Being Assigned From
 This Location
 Incident Map Book Reference: 7J/231
 Incident Station Ground: E35
S.40
 START Group - Resources Being Assigned
 From Other Location:
 END Group - Resources Being Assigned From
 Other Location
 START Group - Assigned Resources:
 Resource Call Sign: E351
 Resource Call Sign: E341
 Resource Call Sign: E381
 Resource Call Sign: OK10
 Resource Call Sign: CU4
 Resource Call Sign: E371
 Resource Call Sign: F121
 Resource Call Sign: F25S
 Resource Call Sign: F63

			Resource Call Sign: F110 Resource Call Sign: A37S END Group - Assigned Resources
17:04:37	MPE		Mobilisation Required response met
17:04:37	MPE		Mobilisation Required response met
17:04:38	SYS		Incident turnout to F90 for OK13 completed [19870]
17:04:39	LOB		Action CML ACTION MATRIX FOR 4 PUMP GRASS FIRE Completed NA
17:04:55	SYS		Incident turnout to F90 for OK13 crew acknowledgement received [19870]
17:04:59	SYS	CU4	Text message to CU4 - The message timed at 17:04 - sent
17:04:59	SYS	OK13	Text message to OK13 - The message timed at 17:04 - sent
17:04:59	MPE	OK10	User Comment .
17:04:59	MPE	OK10	Status changed from R - Committed To Incident to P - Available by pager
17:04:59	MPE	OK10	Clear from Incident Inc No. -01012023
17:05:02	SYS	CU4	Text message to CU4 [19874] completed
17:05:14	MPE	OK13	Status changed from R - Committed To Incident to 2 - Proceeding to incident
17:05:43	SYS		Incident turnout to OK13 for OK13 no crew acknowledgement received [19873]
17:05:48	MPE		Linked as parent of 000513-01012023 (4PF FIRECOVER)
17:05:52	SYS	CU4	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:05:53	VB1	F63	User Comment Acknowledged receipt of incident Inc No. -01012023
17:05:54	VB1	F63	F63 not proceeding to incident
17:05:56	EK		Key POLICE REQUESTED FOR TRAFFIC CONTROL 6062
17:05:56	SYS		Incident turnout to OK13 for OK13 failed [19873]
17:06:11	MC		Mobilisation Turnout Methods Offered F121 : [P] V
17:06:11	MC	F121	Status changed from P - Available by Paging to R - Committed
17:06:11	MC	F121	Role set to GC
17:06:11	MC	F121	Assigned to Incident Inc No. -01012023
17:06:11	MC		Mobilisation Required response met
17:06:11	MC		Mobilisation MC Turnout F121 (P) to Inc No. -01012023
17:06:11	MC		Mobilisation Required response met
17:06:12	SYS		Incident turnout to F121 for F121 completed [19879]
17:06:13	VB1		Agency F63 RESPONDED AND MONITORING AS ORT
17:06:31	KB1		OtherAgencyCallRef set to TFL REF 311
17:06:32	EK		000514-01012023 identified as a repeat of this incident

17:06:51	KH		Mobilisation Turnout Methods Offered A37S : [P] V
17:06:51	KH	A37S	Status changed from P - Available by Paging to R - Committed
17:06:51	KH	A37S	Role changed from STATION COMMANDER to SC
17:06:51	KH	A37S	Assigned to Incident Inc No. -01012023
17:06:51	KH		Mobilisation Required response met
17:06:51	KH		Mobilisation KH Turnout A37S (P) to Inc No. -01012023
17:06:51	KH		Mobilisation Required response met
17:06:51	KH		User Comment FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL * * PERSONS REPORTED BY CONTROL S.41 FLOOR * *
			Turning out with message - A37S RESPONDED TO PAGER - A37S SELF MOBILISED AS PR OFFICER
17:06:52	SYS		Incident turnout to A37S for A37S completed [19883]
17:06:54	KH	A37S	User Comment Acknowledged receipt of incident Inc No. -01012023
17:07:01	KH		Agency A37S RESPONDED TO PAGER - A37S SELF MOBILISED AS PR OFFICER
17:07:03	EOG	F110	User Comment Acknowledged receipt of incident Inc No. -01012023
17:07:04	EOG	F110	F110 not proceeding to incident
17:07:04	KH	A37S	Status changed from R - Committed to 2 - Proceeding to incident
17:07:05	MC		Informative SPOKE WITH F121 AND ADVISED THAT HE MAY WANT TO ATTEND AS SFSO - HE IS ATTENDING WITH G37S SHADOWING
17:07:09	MC	F121	Status changed from R - Committed to 2 - Proceeding to incident
17:07:18	TS3		Make Up IUP E351 REQ ATTENDANCE OF TL ANY HEIGHT
17:07:34	LOB		Service Request Service Request Updated from IUP E351 REQ ATTENDANCE OF TL ANY HEIGHT , to LO - IUP E351 REQ ATTENDANCE OF TL ANY HEIGHT
17:07:38	MPE		Service Request Service Request InProgress: LO - IUP E351 REQ ATTENDANCE OF TL ANY HEIGHT
17:07:39	KB1		000515-01012023 identified as a repeat of this incident
17:07:44	LOB		Details changed from FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL * * PERSONS REPORTED BY CONTROL S.41 FLOOR * * to FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL TL REQUESTED FROM SCENE * * PERSONS REPORTED BY CONTROL S.41 FLOOR * *

17:07:44	LOB		Incident details update sent to OK13
17:07:49	MC		Mobilisation Turnout Methods Offered G37S : [P] V
17:07:49	MC	G37S	Status changed from P - Available by Paging to R - Committed
17:07:49	MC	G37S	Role set to SC
17:07:49	MC	G37S	Assigned to Incident Inc No. -01012023
17:07:49	MC		Mobilisation Required response met
17:07:49	MC		Mobilisation MC Turnout G37S (P) to Inc No. -01012023
17:07:49	MC		Mobilisation Required response met
17:07:49	MC		User Comment FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL * * PERSONS REPORTED BY CONTROL S.41 FLOOR * *
17:07:50	SYS		Turning out with message - G37S AS SFSO SHADOW Incident turnout to G37S for G37S completed [19900]
17:07:56	SYS	OK13	Text message to OK13 [19875] failed
17:08:04	LOB		Mobilisation Turnout Methods Offered E354 : [W] [M] V
17:08:04	LOB	E354	Officer In Charge changed from to S.40 LFF
17:08:04	LOB	E354	Riders changed from 0 to 2
17:08:04	LOB	E354	Status changed from 1 - At Station to R - Committed To Incident
17:08:04	LOB	E354	Assigned to Incident Inc No. -01012023
17:08:04	LOB	E354	Role changed from AERIAL LADDER to TL
17:08:04	LOB		Mobilisation LOB Turnout E354 (W),E354 (M) to Inc No. -01012023
17:08:04	LOB	E35	Mobilisation Make Up - Makeup
			Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: A1 Incident Type: PR Incident Type: 4PF Incident Details: FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL TL REQUESTED FROM SCENE * * PERSONS REPORTED BY CONTROL S.41 FLOOR * * Incident Address: , No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: E354 Resource Attribute Codes: TL END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: END Group - Resources Being Assigned From

			Other Location
			START Group - Assigned Resources:
			Resource Call Sign: E351
			Resource Call Sign: E341
			Resource Call Sign: E381
			Resource Call Sign: CU4
			Resource Call Sign: E371
			Resource Call Sign: OK13
			Resource Call Sign: F121
			Resource Call Sign: F25S
			Resource Call Sign: F63
			Resource Call Sign: F110
			Resource Call Sign: A37S
			Resource Call Sign: F121
			Resource Call Sign: G37S
			END Group - Assigned Resources
17:08:04	LOB		Mobilisation
			Required response met
17:08:04	LOB		Mobilisation
			Required response met
17:08:05	SYS		Incident turnout to E35 for E354 completed [19902]
17:08:07	SYS		Incident turnout to E354 for E354 completed [19905]
17:08:24	MC		Agency
			G37S MOBILISED AS SHADOWING SFSO
17:08:29	LOB	E351	Make Up
			Make TURNTABLE LADDER 1 Requested
17:08:29	SYS	OK13	Text message to OK13 - The message timed at 17:08 - sent
17:08:29	SYS	E354	Text message to E354 - The message timed at 17:08 - sent
17:08:30	SYS	E354	Text message to E354 [19907] completed
17:08:57	LOB	E351	Make Up
			Make AERIAL SUPPORT PUMP 1 Requested
17:08:57	SYS	OK13	Text message to OK13 - The message timed at 17:08 - sent
17:08:57	SYS	E354	Text message to E354 - The message timed at 17:08 - sent
17:08:58	SYS	E354	Text message to E354 [19909] completed
17:09:01	SYS		Incident turnout to E354 for E354 crew acknowledgement received [19905]
17:09:04	SYS	E354	Status changed from R - Committed To Incident to 2 - Proceeding to incident
17:09:04	SYS	E354	Officer In Charge changed from S.40 LFF to -
17:09:05	SYS		Incident turnout to OK13 for OK13 failed [19898]
17:09:10	SYS		Incident turnout to E35 for E354 no crew acknowledgement received [19902]
17:09:47	LOB	E354	Officer In Charge changed from S.40 to - LFF
17:09:47	LOB	E354	Role changed from TL to TURNTABLE LADDER
17:09:48	MPE	A37S	Role changed from SC to PRESS LIAISON
17:09:55	KR	G37S	Role changed from SC to FIRE SAFETY OFFICER SHADOW
17:10:04	LOB		Mobilisation Turnout Methods Offered
			E221 : [W] [M] V
			OK13 : [M] V
17:10:04	LOB	E221	Officer In Charge changed from to S.40
			SUBO
17:10:04	LOB	E221	Riders changed from 0 to 5

17:10:04	LOB	E221	Status changed from 1 - At Station to R - Committed To Incident
17:10:04	LOB	E221	Assigned to Incident Inc No. -01012023
17:10:04	LOB	E221	Role changed from PUMPING APPLIANCE to AERIAL SUPPORT PUMP
17:10:04	LOB	OK13	Role changed from FIU to FIRE INVESTIGATION UNIT,FIU
17:10:04	LOB		Mobilisation LOB Turnout E221 (W),E221 (M),OK13 (M) to Inc No. -01012023
17:10:04	LOB	E22	Mobilisation Make Up - Makeup
			Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: A1 Incident Type: PR Incident Type: 4PF Incident Details: FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL TL REQUESTED FROM SCENE * * PERSONS REPORTED BY CONTROL S.41 FLOOR * * Incident Address: No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: E221 Resource Attribute Codes: ASP END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: Resource Call Sign: OK13 Resource Attribute Codes: FIU Resource Attribute Codes: FIU END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: E351 Resource Call Sign: E341 Resource Call Sign: E381 Resource Call Sign: CU4 Resource Call Sign: E371 Resource Call Sign: E354 Resource Call Sign: F121 Resource Call Sign: F25S Resource Call Sign: F63 Resource Call Sign: F110 Resource Call Sign: A37S Resource Call Sign: F121 Resource Call Sign: G37S END Group - Assigned Resources
17:10:04	LOB		Mobilisation Required response met
17:10:04	LOB		Mobilisation Required response met
17:10:06	SYS		Incident turnout to E22 for E221 completed [19918]
17:10:08	SYS		Incident turnout to E221 for E221 completed [19921]

17:10:16	MPE	F121	Role changed from GC to FIRE SAFETY OFFICER
17:10:17	SYS	OK13	Text message to OK13 [19906] failed
17:10:26	SYS		Incident turnout to E221 for E221 crew acknowledgement received [19921]
17:10:35	TS3		Key CU4 REQ TL TO COME FROM THE DIRECTION OF ELEPHANT ANC CASTLE DUE TO TRAFFIC CONDITIONS
17:10:52	LOB		Service Request Service Request Created: RT5 - E354 - FYI E221 HAS BEEN ORDERED AS YOUR ASP
17:11:10	SYS		Incident turnout to E22 for E221 no crew acknowledgement received [19918]
17:11:10	SYS		Incident turnout to OK13 for OK13 no crew acknowledgement received [19924]
17:11:14	SYS	E221	Action Prompt E221 (E22) not booked mobile to incident displayed to All
17:11:16	TS3		Details changed from FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL TL REQUESTED FROM SCENE * * PERSONS REPORTED BY CONTROL S.41 FLOOR * * to FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL TL REQUESTED FROM SCENE * * PERSONS REPORTED BY CONTROL S.41 FLOOR * * **TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE**
17:11:16	TS3		Incident details update sent to OK13,E354,E221
17:11:16	LOB		Service Request Service Request Completed: LO - IUP E351 FROM SUB S.41 MAKE PUMPS FOUR PERSONS REPORTED REQ URGENT ATTENDANCE OF POLICE FOR TRAFFIC CONTROL
17:11:19	SYS		Incident turnout to OK13 for OK13 failed [19924]
17:11:22	LOB		Service Request Service Request Completed: LO - IUP E351 REQ ATTENDANCE OF TL ANY HEIGHT
17:11:50	SYS	E221	Status changed from R - Committed To Incident to 2 - Proceeding to incident
17:11:50	SYS	E221	Officer In Charge changed from S.40 SUBO to -
17:12:06	TS3		Informative CU4 CU4 IS ICV
17:12:20	TS3		Service Request Service Request Completed: CU4 REQ TL TO COME FROM THE DIRECTION OF ELEPHANT ANC CASTLE DUE TO TRAFFIC CONDITIONS
17:12:26	SYS		Incident turnout to E354 for E354 failed [19934]
17:12:26	SYS		Incident turnout to E221 for E221 failed [19938]
17:12:26	SYS		Incident turnout to OK13 for OK13 failed [19930]
17:12:29	LOB		Action INFORM TWA IF INCIDENT IS WITHIN TWA AREA Completed 1022237623
17:13:06	TS3		Service Request Service Request Completed: RT5 - E354 - FYI E221 HAS BEEN ORDERED AS YOUR ASP
17:13:23	TS3		Service Request Service Request Comment for RT5 - E354 - FYI

			E221 HAS BEEN ORDERED AS YOUR ASP updated to: PASSED TO CU4
17:13:39	SYS	OK13	Text message to OK13 [19908] failed
17:13:43	TS3	OK13	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:14:09	TS3	F25S	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:15:47	TS3	G37S	Status changed from R - Committed to 2 - Proceeding to incident
17:17:06	MPE		Details changed from FOUR PUMP FIRE - MULTIPLE CALLS ADDITIONAL TL REQUESTED FROM SCENE
			** PERSONS REPORTED BY CONTROL S.41
			FLOOR ** **TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** to FOUR PUMP FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE
			** TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL
17:17:06	MPE		Incident details update sent to E354,E221
17:17:09	SYS		Incident turnout to E354 for E354 completed [20022]
17:17:21	MPE		Additional Type FSG added
17:17:21	MPE		Action
			Action Plan 2670 Activated
17:17:21	MPE		Tag FSG added
17:17:23	SYS		Incident turnout to E221 for E221 completed [20025]
17:17:39	MPE		Mobilisation Turnout Methods Offered
			CU5 : [W] [M] V
			G24S : [P] V
			H241 : [W] [M] V
17:17:39	MPE	CU5	Officer In Charge changed from to S.40
			STNO
17:17:39	MPE	CU5	Riders changed from 0 to 4
17:17:39	MPE	CU5	Status changed from 1 - At Station to R - Committed To Incident
17:17:39	MPE	CU5	Assigned to Incident Inc No. -01012023
17:17:39	MPE	CU5	Role changed from COMMAND UNIT to FSG CU
17:17:39	MPE	H241	Officer In Charge changed from to S.40
			STNO
17:17:39	MPE	H241	Riders changed from 0 to 4
17:17:39	MPE	H241	Status changed from 1 - At Station to R - Committed To Incident
17:17:39	MPE	H241	Assigned to Incident Inc No. -01012023
17:17:39	MPE	H241	Role changed from PUMPING APPLIANCE,LONDON PUMPING APPLIANCE,135 LADDER,SUB OR STN OFFICER to SUB OR STN OFFICER (FSG)
17:17:39	MPE	G24S	Status changed from P - Available by Paging to R - Committed
17:17:39	MPE	G24S	Role changed from STATION COMMANDER to FIRE SURVIVAL GUIDANCE SC
17:17:39	MPE	G24S	Assigned to Incident Inc No. -01012023
17:17:39	MPE		Mobilisation MPE
			Turnout CU5 (W),CU5 (M),H241 (W),H241 (M) to Inc No. -01012023

17:17:39	MPE	E31	Mobilisation Make Up - Makeup Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: A1 Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Details: FOUR PUMP FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL Incident Address: , No. OLD KENT ROAD, LONDON, SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: CU5 Resource Attribute Codes: FSGC END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: Resource Call Sign: H241 Resource Attribute Codes: FSGPA Resource Call Sign: G24S Resource Attribute Codes: FSGS END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: E351 Resource Call Sign: E341 Resource Call Sign: E381 Resource Call Sign: CU4 Resource Call Sign: E371 Resource Call Sign: OK13 Resource Call Sign: E354 Resource Call Sign: E221 Resource Call Sign: F121 Resource Call Sign: F25S Resource Call Sign: F63 Resource Call Sign: F110 Resource Call Sign: A37S Resource Call Sign: F121 Resource Call Sign: G37S END Group - Assigned Resources
17:17:39	MPE	H24	Mobilisation Make Up - Makeup Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: A1 Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Details: FOUR PUMP FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL Incident Address: , No.

			OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: H241 Resource Attribute Codes: FSGPA END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: Resource Call Sign: CU5 Resource Attribute Codes: FSGC Resource Call Sign: G24S Resource Attribute Codes: FSGS END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: E351 Resource Call Sign: E341 Resource Call Sign: E381 Resource Call Sign: CU4 Resource Call Sign: E371 Resource Call Sign: OK13 Resource Call Sign: E354 Resource Call Sign: E221 Resource Call Sign: F121 Resource Call Sign: F25S Resource Call Sign: F63 Resource Call Sign: F110 Resource Call Sign: A37S Resource Call Sign: F121 Resource Call Sign: G37S END Group - Assigned Resources
17:17:39	MPE		Mobilisation Required response met
17:17:39	MPE		Mobilisation MPE Turnout G24S (P) to Inc No. -01012023
17:17:39	MPE		Mobilisation Required response met
17:17:39	SYS		Incident turnout to E31 for CU5 crew
17:17:39	SYS		acknowledgement received [20028]
17:17:39	SYS		Incident turnout to H24 for H241 crew
17:17:39	SYS		acknowledgement received [20031]
17:17:43	SYS		Incident turnout to G24S for G24S completed
17:17:43	SYS		[20041]
17:18:36	SYS	H241	Status changed from R - Committed To Incident
17:18:36	SYS	H241	to 2 - Proceeding to incident
17:18:36	SYS	H241	Officer In Charge changed from 47270E STNO
17:18:36	SYS	H241	to -
17:18:40	SYS	CU5	Action Prompt CU5 (E31) not alerted displayed
17:18:40	SYS	CU5	to All
17:18:40	SYS	CU5	Incident turnout to CU5 for CU5 failed [20035]
17:18:40	SYS	CU5	Incident turnout to H241 for H241 failed [20039]
17:18:44	SYS	CU5	Action Prompt CU5 (E31) not booked mobile to
17:18:44	SYS	CU5	incident displayed to All
17:20:01	KH	G24S	Status changed from R - Committed to 2 -
17:20:01	KH	G24S	Proceeding to incident
17:20:03	SYS	CU5	Status changed from R - Committed To Incident
17:20:03	SYS	CU5	to 2 - Proceeding to incident
17:20:03	SYS	CU5	Officer In Charge changed from S.41 STNO
17:20:03	SYS	CU5	to -

17:20:04	SYS	E221	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:24:25	TS3		Informative SUP CU4 FROM SUBO S.41 AT No. OLD KENT ROAD A MID TERRACE SHOP AND DWELLINGS OF 3 FLOORS 5M X 10M S.40 S.40 S.40 S.40 S.40 S.40 S.40 S.40 S.40 2 JETS 1 HR 2BA STAGE 1 ENTRY CONTROL TIC MDT TMO
17:24:44	SYS	H241	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:24:54	TS3		Informative AMMENDMENT S.40 FLAT ALIGHT
17:25:26	TS3		Informative SUP CU4 SC S.40 NOW IC
17:26:19	MPE		Key RTE/CU4 - FSG ATTENDANCE HAS BEEN MOBILISED
17:28:21	TS3	A37S	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:28:23	TS3	F121	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:28:25	TS3	G37S	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:28:36	SW2		Mobilisation Turnout Methods Offered F110 : [P] V
17:28:36	SW2	F110	Status changed from P - Available by Paging to R - Committed
17:28:36	SW2	F110	Role changed from HAZARDOUS MATERIALS to GC
17:28:36	SW2	F110	Assigned to Incident Inc No. -01012023
17:28:36	SW2		Mobilisation Required response met
17:28:36	SW2		Mobilisation SW2 Turnout F110 (P) to Inc No. -01012023
17:28:36	SW2		Mobilisation Required response met
17:28:36	SW2		User Comment FOUR PUMP FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL Turning out with message - GC F110 ATTENDING AS GC
17:28:37	SYS		Incident turnout to F110 for F110 completed [20095]
17:28:55	SW2	F110	Status changed from R - Committed to 2 - Proceeding to incident
17:30:03	SW2	E1	Informed of incident Inc No. -01012023
17:30:03	SW2		Mobilisation Inform E1 (P) of Inc No. -01012023
17:30:03	SW2		User Comment FOUR PUMP FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF

ELEPHANT AND CASTLE - PERSONS REPORTED BY CONTROL**

			Turning out with message - DAC E1 PAGED TO INFORM GC F110 ATTENDING INCIDENT Inform to E1 for E1 completed [20098]
17:30:05	SYS		
17:30:15	SW2		Agency DAC E1 PAGED TO INFORM GC F110 ATTENDING INCIDENT
17:30:20	KH	E1	Informed of incident Inc No. -01012023
17:30:20	KH		Mobilisation Inform E1 (P) of Inc No. -01012023
17:30:20	KH		User Comment FOUR PUMP FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL
			Turning out with message - E1 PAGED AS DAC Inform to E1 for E1 completed [20100]
17:30:21	SYS		
17:30:27	KH		Agency E1 PAGED AS DAC
17:30:39	SW2		Agency GC F110 ATTENDING AS GC
17:31:32	MPE		Service Request Service Request Completed: AMMENDMENT S.41 OF FLAT ALIGHT
17:31:42	MPE		Service Request Service Request Completed: SUP CU4 SC S.40 NOW IC
17:33:28	TS3		Service Request Service Request Completed: RTE/CU4 - FSG ATTENDANCE HAS BEEN MOBILISED
17:34:37	SYS	CU5	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:36:52	TS3		Informative SUP CU4 FSG AT S.40 HAS NOW BEEN COMPLETED BY BA CREWS AT 1730 HOURS
17:37:19	TS3		Informative SUP CU4 H241 IS NOW FSG PUMP
17:39:14	SR2	E1	User Comment Acknowledged receipt of incident Inc No. - 01012023
17:39:15	SR2	E1	E1 not proceeding to incident
17:39:19	TS3	G24S	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:39:26	TS3	F110	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:39:32	SR2		Agency E1 - ACKNOWLEDGED AND MONITORING
17:42:51	TS3	G24S	In Att Time changed from 01/01/2023 17:39:19 to 01/01/2023 17:42:43
17:43:27	TS3		Key G24S BOOKED STATUS 3 IN ERROR G24S STATUS 3 AS OFF 1742
17:45:03	MPE		Service Request Service Request Completed: SUP CU4 H241 IS NOW FSG PUMP
17:45:14	MPE		Service Request Service Request Completed: SUP CU4 FSG AT

			S.40 HAS NOW BEEN COMPLETED BY BA CREWS AT 1730 HOURS
17:53:16	OH1		Make Up IUP - CU4 - FROM SC S.40 - MAKE PUMPS 6 FOR BA - NO FURTHER SENIOR OFFICERS REQUIRED TO ATTEND INCIDENT
17:53:26	EK		Service Request Service Request Updated from IUP - CU4 - FROM SC S.40 - MAKE PUMPS 6 FOR BA - NO FURTHER SENIOR OFFICERS REQUIRED TO ATTEND INCIDENT , to E/IUP - CU4 - FROM SC S.40 - MAKE PUMPS 6 FOR BA - NO FURTHER SENIOR OFFICERS REQUIRED TO ATTEND INCIDENT
17:53:29	EK		Service Request Service Request Updated from E/IUP - CU4 - FROM SC S.40 - MAKE PUMPS 6 FOR BA - NO FURTHER SENIOR OFFICERS REQUIRED TO ATTEND INCIDENT , to EK/IUP - CU4 - FROM SC S.40 - MAKE PUMPS 6 FOR BA - NO FURTHER SENIOR OFFICERS REQUIRED TO ATTEND INCIDENT
17:53:31	EK		Service Request Service Request InProgress: EK/IUP - CU4 - FROM SC S.40 - MAKE PUMPS 6 FOR BA - NO FURTHER SENIOR OFFICERS REQUIRED TO ATTEND INCIDENT
17:54:01	EK	CU4	Additional Type 6PF added
17:54:01	EK		Action Action Plan 2755 Activated
17:54:01	EK		Tag 6PF added
17:54:28	EK		Mobilisation Turnout Methods Offered F331 : [W] [M] V E361 : [W] [M] V CU3 : [W] [M] V OF64 : [P] V F110 : [P] V
17:54:28	EK	F331	Status changed from 5 - Committed To Standby to R - Committed To Incident
17:54:28	EK	F331	Clear from Incident 000513-01012023
17:54:28	EK	F331	Assigned to Incident Inc No. -01012023
17:54:28	EK	F331	Role changed from PL to PUMPING APPLIANCE,SUB OR STN OFFICER
17:54:28	EK	E361	Officer In Charge changed from to S.40 SUBO
17:54:28	EK	E361	Riders changed from 0 to 5
17:54:28	EK	E361	Status changed from 1 - At Station to R - Committed To Incident
17:54:28	EK	E361	Assigned to Incident Inc No. -01012023
17:54:28	EK	E361	Role changed from PUMPING APPLIANCE to PUMPING APPLIANCE,SUB OR STN OFFICER
17:54:28	EK	CU3	Officer In Charge changed from to S.40 STNO
17:54:28	EK	CU3	Riders changed from 0 to 3
17:54:28	EK	CU3	Status changed from 1 - At Station to R - Committed To Incident
17:54:28	EK	CU3	Assigned to Incident Inc No. -01012023
17:54:28	EK	OF64	Status changed from P - Available by Paging to R - Committed
17:54:28	EK	OF64	Assigned to Incident Inc No. -01012023

17:54:28	EK	F110	Role changed from GC to GROUP COMMANDER,GC
17:54:28	EK		Mobilisation EK Turnout F331 (W),F331 (M),E361 (W),E361 (M),CU3 (W),CU3 (M) to Inc No. -01012023
17:54:28	EK	F33	Mobilisation Make Up - Makeup

Incident Number: Inc No. -01012023
 Incident Call Date/Time: 01/01/2023 16:55:30
 Incident Type: A1
 Incident Type: PR
 Incident Type: 4PF
 Incident Type: FSG
 Incident Type: 6PF
 Incident Details: FOUR PUMP FIRE FSG CALL
 IN PROGRESS - TL REQUESTED FROM SCENE
 * * TL TO APPROACH FROM DIRECTION OF
 ELEPHANT AND CASTLE** - PERSONS
 REPORTED BY CONTROL
 Incident Address: , No.
 OLD KENT ROAD,LONDON,SE1 5LU
 START Group - Resources Being Assigned
 From This Location:
 Resource Call Sign: F331
 Resource Attribute Codes: PA
 Resource Attribute Codes: SUBSTNO
 END Group - Resources Being Assigned From
 This Location
 Incident Map Book Reference: 7J/231
 Incident Station Ground: E35
 S.40
 START Group - Resources Being Assigned
 From Other Location:
 Resource Call Sign: E361
 Resource Attribute Codes: PA
 Resource Attribute Codes: SUBSTNO
 Resource Call Sign: CU3
 Resource Attribute Codes: CU
 Resource Call Sign: F110
 Resource Attribute Codes: GC
 Resource Attribute Codes: GC
 Resource Call Sign: F110
 Resource Attribute Codes: GC
 Resource Attribute Codes: GC
 Resource Call Sign: OF64
 Resource Attribute Codes: SC
 END Group - Resources Being Assigned From
 Other Location
 START Group - Assigned Resources:
 Resource Call Sign: E351
 Resource Call Sign: E341
 Resource Call Sign: E381
 Resource Call Sign: CU4
 Resource Call Sign: E371
 Resource Call Sign: OK13
 Resource Call Sign: E354
 Resource Call Sign: E221
 Resource Call Sign: CU5
 Resource Call Sign: H241
 Resource Call Sign: F121
 Resource Call Sign: F25S
 Resource Call Sign: F63
 Resource Call Sign: A37S
 Resource Call Sign: F121

17:54:28 EK E36

Resource Call Sign: G37S
Resource Call Sign: G24S
Resource Call Sign: E1
END Group - Assigned Resources
Mobilisation
Make Up - Makeup

Incident Number: Inc No. -01012023
Incident Call Date/Time: 01/01/2023 16:55:30
Incident Type: A1
Incident Type: PR
Incident Type: 4PF
Incident Type: FSG
Incident Type: 6PF
Incident Details: FOUR PUMP FIRE FSG CALL
IN PROGRESS - TL REQUESTED FROM SCENE
* * TL TO APPROACH FROM DIRECTION OF
ELEPHANT AND CASTLE** - PERSONS
REPORTED BY CONTROL
Incident Address: No.
OLD KENT ROAD, LONDON, SE1 5LU
START Group - Resources Being Assigned
From This Location:
Resource Call Sign: E361
Resource Attribute Codes: PA
Resource Attribute Codes: SUBSTNO
END Group - Resources Being Assigned From
This Location
Incident Map Book Reference: 7J/231
Incident Station Ground: E35
S.40

START Group - Resources Being Assigned
From Other Location:
Resource Call Sign: F331
Resource Attribute Codes: PA
Resource Attribute Codes: SUBSTNO
Resource Call Sign: CU3
Resource Attribute Codes: CU
Resource Call Sign: F110
Resource Attribute Codes: GC
Resource Attribute Codes: GC
Resource Call Sign: F110
Resource Attribute Codes: GC
Resource Attribute Codes: GC
Resource Call Sign: OF64
Resource Attribute Codes: SC
END Group - Resources Being Assigned From
Other Location
START Group - Assigned Resources:
Resource Call Sign: E351
Resource Call Sign: E341
Resource Call Sign: E381
Resource Call Sign: CU4
Resource Call Sign: E371
Resource Call Sign: OK13
Resource Call Sign: E354
Resource Call Sign: E221
Resource Call Sign: CU5
Resource Call Sign: H241
Resource Call Sign: F121
Resource Call Sign: F25S
Resource Call Sign: F63
Resource Call Sign: A37S
Resource Call Sign: F121
Resource Call Sign: G37S

17:54:28 EK F45

Resource Call Sign: G24S
 Resource Call Sign: E1
 END Group - Assigned Resources
 Mobilisation
 Make Up - Makeup

Incident Number: Inc No. -01012023
 Incident Call Date/Time: 01/01/2023 16:55:30
 Incident Type: A1
 Incident Type: PR
 Incident Type: 4PF
 Incident Type: FSG
 Incident Type: 6PF
 Incident Details: FOUR PUMP FIRE FSG CALL
 IN PROGRESS - TL REQUESTED FROM SCENE
 * * TL TO APPROACH FROM DIRECTION OF
 ELEPHANT AND CASTLE** - PERSONS
 REPORTED BY CONTROL
 Incident Address: , No.
 OLD KENT ROAD,LONDON,SE1 5LU
 START Group - Resources Being Assigned
 From This Location:
 Resource Call Sign: CU3
 Resource Attribute Codes: CU
 END Group - Resources Being Assigned From
 This Location
 Incident Map Book Reference: 7J/231
 Incident Station Ground: E35
 S.40

START Group - Resources Being Assigned
 From Other Location:
 Resource Call Sign: F331
 Resource Attribute Codes: PA
 Resource Attribute Codes: SUBSTNO
 Resource Call Sign: E361
 Resource Attribute Codes: PA
 Resource Attribute Codes: SUBSTNO
 Resource Call Sign: F110
 Resource Attribute Codes: GC
 Resource Attribute Codes: GC
 Resource Call Sign: F110
 Resource Attribute Codes: GC
 Resource Attribute Codes: GC
 Resource Call Sign: OF64
 Resource Attribute Codes: SC
 END Group - Resources Being Assigned From
 Other Location
 START Group - Assigned Resources:
 Resource Call Sign: E351
 Resource Call Sign: E341
 Resource Call Sign: E381
 Resource Call Sign: CU4
 Resource Call Sign: E371
 Resource Call Sign: OK13
 Resource Call Sign: E354
 Resource Call Sign: E221
 Resource Call Sign: CU5
 Resource Call Sign: H241
 Resource Call Sign: F121
 Resource Call Sign: F25S
 Resource Call Sign: F63
 Resource Call Sign: A37S
 Resource Call Sign: F121
 Resource Call Sign: G37S
 Resource Call Sign: G24S

			Resource Call Sign: E1
			END Group - Assigned Resources
17:54:28	EK		Mobilisation EK
			Turnout OF64 (P),F110 (P) to Inc No. -01012023
17:54:29	EK		Mobilisation
			Required response met
17:54:29	SYS		Incident turnout to E36 for E361 crew
			acknowledgement received [20246]
17:54:29	SYS		Incident turnout to F45 for CU3 crew
			acknowledgement received [20249]
17:54:29	SYS		Incident turnout to F33 for F331 crew
			acknowledgement received [20243]
17:54:29	EK		Mobilisation
			Required response met
17:54:33	SYS		Incident turnout to OF64 for OF64 completed
			[20263]
17:54:33	SYS		Incident turnout to F110 for F110 completed
			[20265]
17:54:38	SYS		Incident turnout to F331 for F331 completed
			[20253]
17:54:46	EK		Details changed from FOUR PUMP FIRE FSG
			CALL IN PROGRESS - TL REQUESTED FROM
			SCENE
			* * TL TO APPROACH FROM DIRECTION OF
			ELEPHANT AND CASTLE** - PERSONS
			REPORTED BY CONTROL to SIX PUMP FIRE
			FIRE FSG CALL IN PROGRESS - TL
			REQUESTED FROM SCENE
			* * TL TO APPROACH FROM DIRECTION OF
			ELEPHANT AND CASTLE** - PERSONS
			REPORTED BY CONTROL
17:54:46	EK		Incident details update sent to
			E354,F331,E361,CU3
17:54:47	SYS		Incident turnout to F331 for F331 crew
			acknowledgement received [20253]
17:55:08	SYS	F331	Status changed from R - Committed To Incident
			to 1 - At Station
17:55:08	SYS	F331	Clear from Incident Inc No. -01012023
17:55:08	SYS	F331	Officer In Charge changed from S.40 SUBO
			to -
17:55:29	SYS	E361	Action Prompt E361 (E36) not alerted displayed
			to All
17:55:29	SYS		Incident turnout to E361 for E361 failed [20257]
17:55:29	SYS	CU3	Action Prompt CU3 (F45) not alerted displayed
			to All
17:55:29	SYS		Incident turnout to CU3 for CU3 failed [20261]
17:55:37	SYS	E361	Action Prompt E361 (E36) not booked mobile to
			incident displayed to All
17:55:37	SYS	CU3	Action Prompt CU3 (F45) not booked mobile to
			incident displayed to All
17:55:56	EK		Action ALERT SPVR TO COMPLETE THEIR
			PART OF ACTION PLAN Completed
			KATE DEALING
17:55:57	SYS		Incident turnout to E354 for E354 failed [20270]
17:55:57	SYS		Incident turnout to F331 for F331 failed [20274]
17:56:05	KR	F63	Informed of incident Inc No. -01012023
17:56:05	KR		Mobilisation
			Inform F63 (P) of Inc No. -01012023
17:56:05	KR		User Comment
			SIX PUMP FIRE FIRE FSG CALL IN PROGRESS

			- TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL
			Turning out with message - PAGED AS ORT Inform to F63 for F63 completed [20289]
17:56:06	SYS		
17:56:12	KR		Action SUPERVISOR INFORM - ORT Completed F63 PAGED
17:56:42	SYS	E354	Text message to E354 - The message timed at 17:56 - sent
17:56:42	SYS	CU3	Text message to CU3 - The message timed at 17:56 - sent
17:56:42	EK	E361	User Comment .
17:56:42	EK	E361	Status changed from R - Committed To Incident to 1 - At Station
17:56:42	EK	E361	Clear from Incident Inc No. -01012023
17:56:42	SYS	CU3	Status changed from R - Committed To Incident to 2 - Proceeding to incident
17:56:42	SYS	CU3	Officer In Charge changed from 50646A STNO to -
17:56:42	SYS	E354	Text message to E354 [20292] completed
17:56:45	SYS		Incident turnout to E361 for E361 failed [20278]
17:56:45	SYS		Incident turnout to CU3 for CU3 failed [20282]
17:56:47	KR	BC02	Informed of incident Inc No. -01012023
17:56:47	KR		Mobilisation Inform BC02 (P) of Inc No. -01012023
17:56:47	SYS	CU3	Text message to CU3 [20293] completed
17:56:48	SYS		Inform to BC02 for BC02 completed [20298]
17:56:57	EK		Mobilisation Turnout Methods Offered F331 : [W] [M] V E361 : [W] [M] V
17:56:57	EK	F331	Officer In Charge changed from to S.40 SUBO
17:56:57	EK	F331	Riders changed from 0 to 5
17:56:57	EK	F331	Status changed from 1 - At Station to R - Committed To Incident
17:56:57	EK	F331	Assigned to Incident Inc No. -01012023
17:56:57	EK	E361	Officer In Charge changed from SUBO to S.40 SUBO
17:56:57	EK	E361	Riders changed from 0 to 5
17:56:57	EK	E361	Status changed from 1 - At Station to R - Committed To Incident
17:56:57	EK	E361	Assigned to Incident Inc No. -01012023
17:56:57	EK		Mobilisation EK Turnout F331 (W),F331 (M),E361 (W),E361 (M) to Inc No. -01012023
17:56:57	EK	F33	Mobilisation Make Up - Makeup
			Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: A1 Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Type: 6PF Incident Details: SIX PUMP FIRE FIRE FSG

CALL IN PROGRESS - TL REQUESTED FROM SCENE

**** TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL**

Incident Address: [REDACTED], [REDACTED], No. [REDACTED]
OLD KENT ROAD, LONDON, SE1 5LU

START Group - Resources Being Assigned From This Location:

Resource Call Sign: F331

Resource Attribute Codes: PA

Resource Attribute Codes: SUBSTNO

END Group - Resources Being Assigned From This Location

Incident Map Book Reference: 7J/231

Incident Station Ground: E35

S.40

START Group - Resources Being Assigned From Other Location:

Resource Call Sign: E361

Resource Attribute Codes: PA

Resource Attribute Codes: SUBSTNO

END Group - Resources Being Assigned From Other Location

START Group - Assigned Resources:

Resource Call Sign: E351

Resource Call Sign: E341

Resource Call Sign: E381

Resource Call Sign: CU4

Resource Call Sign: E371

Resource Call Sign: OK13

Resource Call Sign: E354

Resource Call Sign: E221

Resource Call Sign: CU5

Resource Call Sign: H241

Resource Call Sign: CU3

Resource Call Sign: F121

Resource Call Sign: F25S

Resource Call Sign: F63

Resource Call Sign: F110

Resource Call Sign: A37S

Resource Call Sign: F121

Resource Call Sign: G37S

Resource Call Sign: G24S

Resource Call Sign: F110

Resource Call Sign: E1

Resource Call Sign: OF64

Resource Call Sign: F63

Resource Call Sign: BC02

END Group - Assigned Resources

Mobilisation

Make Up - Makeup

Incident Number: [Inc No.] -01012023

Incident Call Date/Time: 01/01/2023 16:55:30

Incident Type: A1

Incident Type: PR

Incident Type: 4PF

Incident Type: FSG

Incident Type: 6PF

Incident Details: SIX PUMP FIRE FIRE FSG

CALL IN PROGRESS - TL REQUESTED FROM SCENE

**** TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS**

17:56:57

EK

E36

			REPORTED BY CONTROL
			Incident Address: [REDACTED], No. [REDACTED]
			OLD KENT ROAD, LONDON, SE1 5LU
			START Group - Resources Being Assigned
			From This Location:
			Resource Call Sign: E361
			Resource Attribute Codes: PA
			Resource Attribute Codes: SUBSTNO
			END Group - Resources Being Assigned From
			This Location
			Incident Map Book Reference: 7J/231
			Incident Station Ground: E35
			S.40 [REDACTED]
			START Group - Resources Being Assigned
			From Other Location:
			Resource Call Sign: F331
			Resource Attribute Codes: PA
			Resource Attribute Codes: SUBSTNO
			END Group - Resources Being Assigned From
			Other Location
			START Group - Assigned Resources:
			Resource Call Sign: E351
			Resource Call Sign: E341
			Resource Call Sign: E381
			Resource Call Sign: CU4
			Resource Call Sign: E371
			Resource Call Sign: OK13
			Resource Call Sign: E354
			Resource Call Sign: E221
			Resource Call Sign: CU5
			Resource Call Sign: H241
			Resource Call Sign: CU3
			Resource Call Sign: F121
			Resource Call Sign: F25S
			Resource Call Sign: F63
			Resource Call Sign: F110
			Resource Call Sign: A37S
			Resource Call Sign: F121
			Resource Call Sign: G37S
			Resource Call Sign: G24S
			Resource Call Sign: F110
			Resource Call Sign: E1
			Resource Call Sign: OF64
			Resource Call Sign: F63
			Resource Call Sign: BC02
			END Group - Assigned Resources
17:56:57	EK		Mobilisation
			Required response met
17:56:57	EK		Mobilisation
			Required response met
17:56:57	SYS		Incident turnout to F33 for F331 crew
			acknowledgement received [20309]
17:56:57	SYS		Incident turnout to E36 for E361 crew
			acknowledgement received [20312]
17:56:59	KR		Action SUPERVISOR INFORM - DUTY BCSM IF
			INCIDENT IS HIGH Completed
			BC02 PAGED
17:57:07	EK	E361	Status changed from R - Committed To Incident
			to 2 - Proceeding to incident
17:57:08	SYS	E361	Officer In Charge changed from S.41 [REDACTED] SUBO
			to -
17:57:18	KR		Action CML ACTION MATRIX FOR 6 PUMP FIRE
			Completed
			LOB

17:57:45	SYS	E354	Text message to E354 - The message timed at 17:57 - sent
17:57:45	SYS	CU3	Text message to CU3 - The message timed at 17:57 - sent
17:57:45	SYS	E361	Text message to E361 - The message timed at 17:57 - sent
17:57:45	OH1	F331	User Comment
17:57:45	OH1	F331	Status changed from R - Committed To Incident to 6 - Immediately available by radio
17:57:45	OH1	F331	Clear from Incident Inc No. -01012023
17:57:47	SYS	E354	Text message to E354 [20323] completed
17:57:47	SYS	CU3	Text message to CU3 [20324] completed
17:57:48	KR	SA3	Informed of incident Inc No. -01012023
17:57:48	KR		Mobilisation
17:57:48	KR		Inform SA3 (P) of Inc No. -01012023
17:57:48	KR		User Comment
			SIX PUMP FIRE FIRE FSG CALL IN PROGRESS
			- TL REQUESTED FROM SCENE
			** TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL
			Turning out with message - 6PF
17:57:49	SYS		Inform to SA3 for SA3 completed [20329]
17:57:55	OH1		Mobilisation Turnout Methods Offered
			F331 : [M] V
17:57:55	OH1	F331	Status changed from 6 - Immediately available by radio to R - Committed To Incident
17:57:55	OH1	F331	Assigned to Incident Inc No. -01012023
17:57:55	OH1		Mobilisation OH1
17:57:55	OH1		Turnout F331 (M) to Inc No. -01012023
17:57:55	OH1		Mobilisation
			Required response met
17:57:55	OH1		Mobilisation
			Required response met
17:57:57	KR		Action SPVR INF DUTY SCI ADVR Completed
			SA3 PAGED
17:58:02	SYS		Incident turnout to F331 for F331 no crew acknowledgement received [20316]
17:58:02	SYS		Incident turnout to E361 for E361 no crew acknowledgement received [20320]
17:58:17	SYS	F331	Action Prompt F331 (35) not alerted displayed to All
17:58:17	SYS		Incident turnout to F331 for F331 failed [20316]
17:58:17	SYS		Incident turnout to E361 for E361 failed [20320]
17:58:19	SYS	E361	Text message to E361 [20325] completed
17:58:20	KR		Action SUPERVISOR INFORM - DUTY BCSM IF FSG CALL(S) LIKEL Completed
			BC02 PAGED
17:58:55	SYS		Incident turnout to F331 for F331 completed [20334]
17:58:58	SYS		Incident turnout to F331 for F331 crew acknowledgement received [20334]
17:59:00	LOB		Agency
			CML - 6PF MATRIX COMPLETED E41S PAGED
			AS OD1
17:59:01	EK		Action ORDER AMBULANCE Completed
			REF 4561

17:59:02	SYS	F331	Status changed from R - Committed To Incident to 2 - Proceeding to incident
17:59:02	SYS	F331	Officer In Charge changed from S.40 SUBO to -
17:59:29	SYS	CU3	Status changed from 2 - Proceeding to incident to 6 - Immediately available by radio
17:59:29	SYS	CU3	Clear from Incident Inc No. -01012023
17:59:29	SYS	CU3	Current Station changed from F45 to F22
17:59:31	SYS	E354	Text message to E354 - The message timed at 17:59 - sent
17:59:31	SYS	E361	Text message to E361 - The message timed at 17:59 - sent
17:59:31	SYS	F331	Text message to F331 - The message timed at 17:59 - sent
17:59:31	EOG	OF64	User Comment
17:59:31	EOG	OF64	.
17:59:31	EOG	OF64	Status changed from R - Committed to P - Available by Paging
17:59:31	EOG	OF64	Clear from Incident Inc No. -01012023
17:59:31	EOG	OF64	Current Station changed from F21 to F40
17:59:32	SYS	E354	Text message to E354 [20347] completed
17:59:32	SYS	E361	Text message to E361 [20348] completed
17:59:32	SYS	F331	Text message to F331 [20349] completed
18:00:03	OH1		Make Up IUP - CU4 - REQ A SECOND FIT UNIT TO INCIDENT
18:00:16	VB1	BC02	User Comment Acknowledged receipt of incident Inc No. -01012023
18:00:17	VB1	BC02	BC02 not proceeding to incident
18:00:19	VB1	SA3	User Comment Acknowledged receipt of incident Inc No. -01012023
18:00:19	VB1	SA3	SA3 not proceeding to incident
18:00:30	EOG		Agency E41S RESPONDING AS OD1 FOR 6PF-MONITORING ON BOSS
18:00:39	KB1		Service Request Service Request Updated from IUP - CU4 - REQ A SECOND FIT UNIT TO INCIDENT , to KB1 IUP - CU4 - REQ A SECOND FIT UNIT TO INCIDENT
18:00:49	VB1		Agency BC02 RESPONDED AND MONITORING
18:01:05	VB1		Agency SA3 RESPONDED AND MONITORING
18:01:12	SR2		Mobilisation Turnout Methods Offered OK15 : [W] [M] V
18:01:12	SR2	OK15	Status changed from 7 - Not immediately available to R - Committed To Incident
18:01:12	SR2	OK15	Assigned to Incident Inc No. -01012023
18:01:12	SR2	OK15	Role changed from FIRE INVESTIGATION UNIT to FIU
18:01:12	SR2		Mobilisation SR2 Turnout OK15 (W),OK15 (M) to Inc No. -01012023
18:01:12	SR2	F90	Mobilisation Make Up - Makeup
			Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30

18:01:13 SR2
 18:01:13 SR2
 18:01:13 SYS
 18:01:26 KR
 18:01:48 KR

Incident Type: A1
 Incident Type: PR
 Incident Type: 4PF
 Incident Type: FSG
 Incident Type: 6PF
 Incident Details: SIX PUMP FIRE FIRE FSG
 CALL IN PROGRESS - TL REQUESTED FROM
 SCENE
 * * TL TO APPROACH FROM DIRECTION OF
 ELEPHANT AND CASTLE** - PERSONS
 REPORTED BY CONTROL
 Incident Address: [REDACTED], No. [REDACTED]
 OLD KENT ROAD, LONDON, SE1 5LU
 START Group - Resources Being Assigned
 From This Location:
 Resource Call Sign: OK15
 Resource Attribute Codes: FIU
 END Group - Resources Being Assigned From
 This Location
 Incident Map Book Reference: 7J/231
 Incident Station Ground: E35
 S.40
 START Group - Resources Being Assigned
 From Other Location:
 END Group - Resources Being Assigned From
 Other Location
 START Group - Assigned Resources:
 Resource Call Sign: E351
 Resource Call Sign: E341
 Resource Call Sign: E381
 Resource Call Sign: CU4
 Resource Call Sign: E371
 Resource Call Sign: OK13
 Resource Call Sign: E354
 Resource Call Sign: E221
 Resource Call Sign: CU5
 Resource Call Sign: H241
 Resource Call Sign: E361
 Resource Call Sign: F331
 Resource Call Sign: F121
 Resource Call Sign: F25S
 Resource Call Sign: F63
 Resource Call Sign: F110
 Resource Call Sign: A37S
 Resource Call Sign: F121
 Resource Call Sign: G37S
 Resource Call Sign: G24S
 Resource Call Sign: F110
 Resource Call Sign: E1
 Resource Call Sign: F63
 Resource Call Sign: BC02
 Resource Call Sign: SA3
 END Group - Assigned Resources
 Mobilisation
 Required response met
 Mobilisation
 Required response met
 Incident turnout to F90 for OK15 crew
 acknowledgement received [20372]
 User Comment
 BC02 RESPONDED AND INFORMED
 Service Request
 Service Request Updated from KB1 IUP - CU4 -
 REQ A SECOND FIT UNIT TO INCIDENT , to KR

			IUP - CU4 - REQ A SECOND FIT UNIT TO INCIDENT
18:01:50	SR2		Agency OK15 ASSIGNED AS SECOND FIRE INVESTIGATION
18:01:55	MPE		Key G24S AND CU5 ARE NOW BEING REDEPLOYED AS PART OF 6PF ATTENDANCE NOW THAT ALL FSG ACTIVITIES ARE CONCLUDED - CU5 NOW INCIDENT COMMAND 2ND CU AND G24S AS ADDITIONAL CU AND CU3/OF64 RETURNED
18:02:02	SR2	OK15	Status changed from R - Committed To Incident to 2 - Proceeding to incident
18:02:13	SYS		Incident turnout to OK15 for OK15 failed [20376]
18:02:31	OH1		Informative SUP - CU4 - FROM SC S.40 - A MID TERRACED SHOP AND DWELLINGS OF 3 FLOORS - 6M X 20M S.40 S.40 S.40 S.40 2 JETS HR 10 BA STAGE 1 ENTRY CONTROL TIC MDT TL USED FOR OBSERVATION TOWER - TMO
18:02:42	KR	CU5	Officer In Charge changed from S.40 to - STNO
18:02:42	KR	CU5	Role changed from FSG CU to COMMAND UNIT
18:03:07	SYS	F331	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
18:03:23	MPE	G24S	Role changed from FIRE SURVIVAL GUIDANCE SC to STATION COMMANDER
18:05:05	KR		Service Request Service Request Completed: KR IUP - CU4 - REQ A SECOND FIT UNIT TO INCIDENT
18:05:22	MPE		Linked as parent of 000554-01012023 (6PF)
18:05:26	KR		User Comment WHILST COMPLETING IUP OK15 SELF MOBILISED - CALLED TO CONFIRM
18:07:36	SB1		Action ORDER WATER SERVICES TECHNICIAN (TURNCOCK) Completed TWA REF - 31920995
18:07:42	SB1		Key TWA REF - 31920995
18:08:07	EK		Service Request Service Request Completed: EK/IUP - CU4 - FROM SC S.40 - MAKE PUMPS 6 FOR BA - NO FURTHER SENIOR OFFICERS REQUIRED TO ATTEND INCIDENT
18:09:02	SB1		Action INFORM POLICE Completed POLICE UPDATED
18:09:21	SB1		Action INFORM POLICE Completed DONE
18:09:43	OH1		Informative CU4 - TCG NOW IN PROGRESS
18:09:44	OH1		Service Request Service Request Completed: CU4 - TCG NOW IN PROGRESS
18:10:52	EK	H26S	Informed of incident Inc No. -01012023
18:10:52	EK		Mobilisation Inform H26S (P) of Inc No. -01012023
18:10:53	SYS		Inform to H26S for H26S completed [20443]

18:11:08	EK		Agency H26S PAGED TO INFORM AS TAB OFFICER
18:11:39	EK		Action INFORM NEAREST TAB OFFR OF FIRES OF 6 PUMPS Completed H26S PAGED AS TAB OFFICER
18:11:44	EK		Action ACTION MP6 Completed ACTIONED
18:12:27	LOB		Agency CML - S.41 FIRE PAGE SENT TO DAC F3, AC F10, STAFF C702
18:12:35	EOG	F63	User Comment Acknowledged receipt of incident Inc No. - 01012023
18:12:36	EOG	F63	F63 not proceeding to incident
18:12:38	EK		Action INFORM DT1 Completed DRONE OFF THE RUN
18:15:02	VB1		Mobilisation Turnout Methods Offered F63 : [P] V
18:15:02	VB1	F63	Status changed from P - Available by Paging to R - Committed
18:15:02	VB1	F63	Role changed from ORT to ORT DUTY
18:15:02	VB1	F63	Assigned to Incident Inc No. -01012023
18:15:02	VB1		Mobilisation Required response met
18:15:02	VB1		Mobilisation VB1 Turnout F63 (P) to Inc No. -01012023
18:15:02	VB1		Mobilisation Required response met
18:15:03	SYS		Incident turnout to F63 for F63 completed [20465]
18:15:11	EK		Agency C702 RESPONDED TO PAGING AND MONITORING
18:15:30	VB1	F63	Status changed from R - Committed to 2 - Proceeding to incident
18:15:38	EOG	H26S	User Comment Acknowledged receipt of incident Inc No. - 01012023
18:15:39	EOG	H26S	H26S not proceeding to incident
18:16:06	SYS	E354	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
18:16:06	SYS	E354	Officer In Charge changed from S.41 LFF to -
18:16:14	EOG		Agency H26S RESPONDED AND MONITORING AS TAB
18:17:50	KR		Details changed from SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - PERSONS REPORTED BY CONTROL to S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** -
18:17:50	KR		Incident details update sent to E361,OK15
18:18:08	SB1		Action INFORM ENVIRONMENT AGENCY Completed ENVIRONMENT AGENCY 2120917
18:18:11	KR	CU4	Additional Type A1F added

18:18:11	KR		Action Action Plan 2710 Activated
18:18:11	KR		Tag A1F added
18:18:18	SB1		Key ENVIRONMENT AGENCY INFORMED 2120917
18:18:23	OH1	OK15	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
18:18:50	SYS		Incident turnout to E361 for E361 failed [20483]
18:18:50	SYS		Incident turnout to OK15 for OK15 failed [20487]
18:19:09	KR		Action CML ACTION MATRIX s.41 FIRE Completed LOB DEALING
18:19:30	KR		Action ALERT SPVR TO COMPLETE THEIR PART OF ACTION PLAN Completed KR
18:20:27	KR		Action IF NO FIU AVAIL INF NEAREST FIU TO LOCN OF FA Completed 2 FIU ATTACHED
18:21:08	KR		Action INFORM SC IF NOT ALREADY ATTENDING Completed NA
18:21:13	KR		Action INFORM GC IF THREE OR MORE s.41 ITIES Completed NA
18:21:57	KR		Action INFORM FS OFFICER IF NOT ALREADY ATTENDING Completed F121 ON SCENE
18:22:12	KR		Action SUPERVISOR INFORM - CML Completed AWARE
18:22:29	KR	PR4	Informed of incident Inc No. -01012023
18:22:29	KR		Mobilisation Inform PR4 (P) of Inc No. -01012023
18:22:30	SYS		Inform to PR4 for PR4 completed [20527]
18:22:42	KR		Action SUPERVISOR INFORM DUTY NON- UNIFORMED PRESS OFFICER Completed PR4 PAGED
18:22:53	KR		Action SUPERVISOR INFORM - DUTY BCSM Completed BC02 INFORMED
18:24:17	TS3		Informative SUP CU4 TCG NOW CONCLUDED NEXT TCG MEETING SCHEDULED FOR 1900 HOURS
18:25:26	KH	PR4	User Comment Acknowledged receipt of incident Inc No. - 01012023
18:25:27	KH	PR4	PR4 not proceeding to incident
18:26:09	LOB		Key CML - s.41 FIRE NOTIFICATION EMAIL SENT
18:26:27	LOB		Key CML - MEMBERS NOTIFICATION SENT TO DUTY AC FOR APPROVAL
18:26:57	99907		Agency F10 RESPONDED AS AC1 TO CONFIRM RECEIPT OF s.41 FIRE NOTIFICATION
18:26:58	KH		Agency PR4 RESPONDED TO PAGER AND MONITORING AS PRESS OFFICER
18:28:38	KR		Action INFORM POLICE Completed UPDATED

18:28:55	KR		Action ACTION s S.41 Completed ACTIONED
18:29:01	KH	G24S	Status changed from 3 - In attendance at an incident to P - Available by Paging
18:29:01	KH	G24S	Clear from Incident Inc No. -01012023
18:29:01	KH	G24S	Current Station changed from G35 to G24
18:30:48	KR		Service Request Service Request Completed: SUP CU4 TCG NOW CONCLUDED NEXT TCG MEETING SCHEDULED FOR 1900 HOURS
18:31:00	KR		Service Request Service Request Completed: SUP - CU4 - FROM SC S.40 - A MID TERRACED SHOP AND DWELLINGS OF 3 FLOORS - 6M X 20M - S S.40 S.40 S.40 2 JETS HR 10 BA STAGE 1 ENTRY CONTROL TIC MDT TL USED FOR OBSERVATION TOWER - TMO
18:32:55	TS3		Informative CU4 FROM SC S.40 FIRE SURROUNDED TMO
18:36:58	TS3	F63	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
18:42:30	TS3		Informative CU4 FROM SC S.40 APAF
18:42:43	TS3		Service Request Service Request Updated from CU4 FROM SC S.40 APAF , to SUP CU4 FROM SC S.40 APAF
18:42:43	TS3		Service Request Service Request Completed: SUP CU4 FROM SC S.40 APAF
18:57:00	TS3		Key SUP/REL CU4 FROM SC S.40 REQ A 2 PUMP RELIEF WITH STNO IN CHARGE FOR CHANGE OF WATCH
18:57:26	KR		Service Request Service Request Updated from SUP/REL CU4 FROM SC S.40 REQ A 2 PUMP RELIEF WITH STNO IN CHARGE FOR CHANGE OF WATCH , to No 2 Watch SUP/REL CU4 FROM SC S.40 REQ A 2 PUMP RELIEF WITH STNO IN CHARGE FOR CHANGE OF WATCH
19:04:34	TS3		Informative CU4 TCG MEETING NOW IN PROGRESS
19:04:59	TS3	E221	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
19:04:59	TS3	E221	Clear from Incident Inc No. -01012023
19:05:17	SYS	E361	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
19:08:33	SYS		Action Prompt Inc No. -01012023(H) under resourced displayed to All
19:08:33	SYS	E354	Status changed from 3 - In attendance at an incident to 6 - Immediately available by radio
19:08:33	SYS	E354	Clear from Incident Inc No. -01012023
19:09:27	TS3	E381	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
19:09:27	TS3	E381	Clear from Incident Inc No. -01012023
19:11:34	SYS	H241	Status changed from 3 - In attendance at an incident to 6 - Immediately available by radio

19:11:34	SYS	H241	Clear from Incident Inc No. -01012023
19:11:34	SYS	H241	Current Station changed from H24 to E35
19:15:24	LOB		Key CML - MEMBERS NOTIFICATION APPROVED AND EMAILED
19:15:43	TS3		Informative CU4 TCG MEETING CONCLUDING NO FURTHER TCGS SCHEDULED
19:16:27	TS3	E371	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
19:16:27	TS3	E371	Clear from Incident Inc No. -01012023
19:17:05	TS3	E351	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
19:17:05	TS3	E351	Clear from Incident Inc No. -01012023
19:19:53	TS3	E341	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
19:19:53	TS3	E341	Clear from Incident Inc No. -01012023
19:20:55	TS3		Key REQ CU4 REQ TWA TO ATTEND THIS INCIDENT TO ISOLATED MAINS SUPPLY COMING INTO BUILDING
19:21:24	LS1		Service Request Service Request Updated from REQ CU4 REQ TWA TO ATTEND THIS INCIDENT TO ISOLATED MAINS SUPPLY COMING INTO BUILDING , to LS1 REQ CU4 REQ TWA TO ATTEND THIS INCIDENT TO ISOLATED MAINS SUPPLY COMING INTO BUILDING
19:21:24	LS1		Service Request Service Request InProgress: LS1 REQ CU4 REQ TWA TO ATTEND THIS INCIDENT TO ISOLATED MAINS SUPPLY COMING INTO BUILDING
19:22:10	VB1		Service Request Service Request Updated from No 2 Watch SUP/REL CU4 FROM SC S.40 REQ A 2 PUMP RELIEF WITH STNO IN CHARGE FOR CHANGE OF WATCH , to ****No 2 Watch**** SUP/REL CU4 FROM SC S.40 REQ A 2 PUMP RELIEF WITH STNO IN CHARGE FOR CHANGE OF WATCH
19:27:11	LS1		Key RT5 - CU4 - TWA TECHNICIAN EN ROUTE ETA WITHIN THE HOUR
19:27:18	LS1		Service Request Service Request Completed: LS1 REQ CU4 REQ TWA TO ATTEND THIS INCIDENT TO ISOLATED MAINS SUPPLY COMING INTO BUILDING
19:27:34	LS1		OtherAgencyCallRef changed from TFL REF 311 to TFL REF 311 TWA 31920995
19:27:42	TS3		Service Request Service Request Completed: RT5 - CU4 - TWA TECHNICIAN EN ROUTE ETA WITHIN THE HOUR
19:40:57	SYS	CU5	Status changed from 3 - In attendance at an incident to 6 - Immediately available by radio
19:40:57	SYS	CU5	Clear from Incident Inc No. -01012023
19:40:57	SYS	CU5	Current Station changed from E31 to E35
19:40:57	SYS	CU5	Officer In Charge changed from S.41 STNO to -

41/65

20:06:52	SAD		Service Request Service Request Completed: E361 FROM SUBO S.41 E361 IS NOW ICP
20:08:10	MC	A37S	Status changed from 3 - In attendance at an incident to P - Available by Paging
20:08:10	MC	A37S	Clear from Incident Inc No. -01012023
20:08:10	MC	A37S	Current Station changed from F24 to A37
20:09:55	SAD	CU4	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
20:09:55	SAD	CU4	Clear from Incident Inc No. -01012023
20:13:25	DE	E232	Relief Added - E232 (Inc No. -01012023) Immediate: False Relief Time: 01/01/2023 22:13:00 Reserve: 30 mins
20:14:15	DE		Relief general text changed to - E232 FOR ONE PUMP RELIEF AS SOON AFTER CHANGE OF WATCH WITH LFF IN CHARGE
20:14:15	DE	E232	Relief Updated - E232 (Inc No. -01012023) Immediate: True Relief Time: 01/01/2023 20:14:13 Reserve: 30 mins Attributes: Not Sent
20:14:25	DE		Mobilisation Turnout Methods Offered E232 : [W] [M] V
20:14:25	DE	E232	Officer In Charge changed from to 49697A LFF
20:14:25	DE	E232	Riders changed from 0 to 4
20:14:25	DE	E232	Status changed from 1 - At Station to R - Committed To Incident
20:14:25	DE	E232	Assigned to Incident Inc No. -01012023
20:14:25	DE	E232	Role changed from PUMPING APPLIANCE to P
20:14:25	DE		Mobilisation DE
20:14:25	DE		Turnout E232 (W),E232 (M) to Inc No. -01012023
20:14:25	DE	E23	Mobilisation Relief - Relief
			Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: A1 Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Type: 6PF Incident Type: A1F Incident Details: S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - START Group - Resources Being Assigned From This Location: Resource Call Sign: E232 Resource Attribute Codes: AS RELIEF NOW END Group - Resources Being Assigned From This Location Incident Address: , No. OLD KENT ROAD,LONDON,SE1 5LU Incident Resource Mobilisation Notes: E232 FOR ONE PUMP RELIEF AS SOON AFTER CHANGE OF WATCH WITH LFF IN CHARGE Incident Map Book Reference: 7J/231

			Incident Station Ground: E35 S.40
			START Group - Resources Being Assigned From Other Location:
			END Group - Resources Being Assigned From Other Location
			START Group - Assigned Resources:
			Resource Call Sign: OK13
			Resource Call Sign: E361
			Resource Call Sign: OK15
			Resource Call Sign: F121
			Resource Call Sign: F25S
			Resource Call Sign: F63
			Resource Call Sign: F110
			Resource Call Sign: F121
			Resource Call Sign: G37S
			Resource Call Sign: E1
			Resource Call Sign: F63
			Resource Call Sign: BC02
			Resource Call Sign: SA3
			Resource Call Sign: H26S
			Resource Call Sign: F63
			Resource Call Sign: PR4
			END Group - Assigned Resources
20:14:25	DE		Mobilisation Required response not despatched 2/SUB OR STN OFFICER, 4/PUMPING APPLIANCE, 2/COMMAND UNIT, 1/FSG CU, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
20:14:25	DE		Mobilisation Required response not despatched 2/SUB OR STN OFFICER, 4/PUMPING APPLIANCE, 2/COMMAND UNIT, 1/FSG CU, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
20:14:25	DE	E232	Relief Sent - E232 (Inc No. S.40 -01012023)
20:14:25	DE		User Comment S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** -
			Turning out with message - E232 FOR ONE PUMP RELIEF AS SOON AFTER CHANGE OF WATCH WITH LFF IN CHARGE
20:14:25	SYS		Incident turnout to E23 for E232 crew acknowledgement received [21144]
20:14:28	SYS		Incident turnout to E232 for E232 completed [21148]
20:14:33	DE		Service Request Service Request Completed: SUP CU4 REQUEST ONE PUMP RELIEF WITH LFF IN CHARGE SOON AFTER CHANGE OF WATCH
20:15:30	SYS		Incident turnout to E232 for E232 no crew acknowledgement received [21148]
20:15:34	SYS	E232	Action Prompt E232 (E23) not booked mobile to incident displayed to All
20:17:00	SYS	E232	Status changed from R - Committed To Incident to 2 - Proceeding to incident
20:17:00	SYS	E232	Officer In Charge changed from S.40 LFF to -
20:28:23	CB		Service Request Service Request Completed: ****No 2 Watch**** SUP/REL CU4 FROM SC S.40 REQ A 1

			PUMP RELIEF WITH Iff IN CHARGE FOR CHANGE OF WATCH
20:28:29	CB		Service Request Service Request Completed: SUP CU4 FROM SUBO S.41 AT No. OLD KENT ROAD A MID TERRACE SHOP AND DWELLINGS OF 3 FLOORS 5M X 10M S.40 S.40 S.40 S.40 S.40 S.40 S.40 2 JETS 1
			HR 2BA STAGE 1 ENTRY CONTROL TIC MDT TMO
20:29:09	JW	OK15	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
20:29:09	JW	OK15	Clear from Incident Inc No. -01012023
20:30:30	GM	F25S	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
20:30:30	GM	F25S	Clear from Incident Inc No. -01012023
20:34:55	JW		Key REQ - E361 - REQUEST ETA FOR WATER AUTHORITY
20:35:52	NT		Service Request Service Request Updated from REQ - E361 - REQUEST ETA FOR WATER AUTHORITY, to nT REQ - E361 - REQUEST ETA FOR WATER AUTHORITY
20:35:52	NT		Service Request Service Request InProgress: nT REQ - E361 - REQUEST ETA FOR WATER AUTHORITY
20:37:52	NT		Stop Resource changed from to CU4
20:39:33	SYS	E232	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
20:50:24	NT		Key TWA NEW REFERENCE 31920998
20:50:35	NT		OtherAgencyCallRef changed from TFL REF 311 TWA 31920995 to TFL REF 311 TWA 31920995 / TWA NEW REFERENCE 31920998
20:51:27	SAD		Informative E232 NOW ICP LFF S.40 IC
20:51:51	NT		Service Request Service Request Created: RT5 E361/E232 TWA STILL HAVE NOT ASSIGNED AN ENGINEER, ONCE ON ROUTE THEY WILL CONTACT WITH AN ETA
20:51:55	SAD	E361	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
20:51:55	SAD	E361	Clear from Incident Inc No. -01012023
20:52:05	NT		Service Request Service Request Completed: nT REQ - E361 - REQUEST ETA FOR WATER AUTHORITY
20:52:37	SAD		Service Request Service Request InProgress: RT5 E361/E232 TWA STILL HAVE NOT ASSIGNED AN ENGINEER, ONCE ON ROUTE THEY WILL CONTACT WITH AN ETA
20:56:57	YA	F63	Status changed from 3 - In attendance at an incident to P - Available by Paging
20:56:57	YA	F63	Clear from Incident Inc No. -01012023

21:19:56	SAD		Service Request Service Request Completed: RT5 E361/E232 TWA STILL HAVE NOT ASSIGNED AN ENGINEER, ONCE ON ROUTE THEY WILL CONTACT WITH AN ETA
21:20:38	SAD	G37S	Status changed from 3 - In attendance at an incident to P - Available by Paging
21:20:38	SAD	G37S	Clear from Incident Inc No. -01012023
21:20:38	SAD	G37S	Current Station changed from F24 to G37
21:22:08	SAD		Revised Type changed from to F
21:23:58	MC	F121	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
21:23:58	MC	F121	Clear from Incident Inc No. -01012023
22:02:03	JW		Key E232 INFORMED BY RT NO INCOMING MESSAGE WAS RECEIVED REGARDING POWER ISOLATED
22:09:00	JW		Key REQ - E232 - REQUEST ETA FOR WATER AUTHORITY
22:09:19	YA		Service Request Service Request Completed: REQ - E232 - REQUEST ETA FOR WATER AUTHORITY
22:09:33	JW		Key TWA EN ROUTE - NO ETA
22:09:41	YA		Key TWA ARE ON WAY NO ETA
22:45:55	SAD	OK13	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
22:45:55	SAD	OK13	Clear from Incident Inc No. -01012023
23:02:24	SAD		Key REQ E232 REQUEST ETA FOR THAMES WATER AS WATER IS DESTROYING EVIDENCE
23:02:29	SAD		Service Request Service Request Completed: REQ E232 REQUEST ETA FOR THAMES WATER AS WATER IS DESTROYING EVIDENCE
23:03:03	YA		Service Request Service Request Updated from REQ E232 REQUEST ETA FOR THAMES WATER AS WATER IS DESTROYING EVIDENCE, to YA REQ E232 REQUEST ETA FOR THAMES WATER AS WATER IS DESTROYING EVIDENCE
23:11:02	YA		Key RT5 E232 ETA OF TWA IS APPROX 30 MINS
23:13:24	SAD		Informative SUP E232 REQUEST ONE PUMP RELIEF MIN LFF IN CHARGE AS SOON AFTER 12:00 HRS AS POSSIBLE
23:13:46	SAD		Service Request Service Request Completed: RT5 E232 ETA OF TWA IS APPROX 30 MINS
23:22:52	SAD		Informative E232 THAMES WATER NOW IN ATTENDANCE
23:23:51	DE	H242	Relief Added - H242 (Inc No. -01012023) Immediate: False Relief Time: 02/01/2023 01:23:00 Reserve: 30 mins
23:24:19	DE		Service Request Service Request Completed: SUP E232 REQUEST ONE PUMP RELIEF MIN LFF IN

			CHARGE AS SOON AFTER 12:00 HRS AS POSSIBLE
23:24:23	DE		Relief general text changed to - H242 FOR ONE PUMP RELIEF AT 00:00 WITH LFF IN CHARGE
23:24:23	DE	H242	Relief Updated - H242 (Inc No. -01012023) Immediate: True Relief Time: 01/01/2023 23:24:07 Reserve: 30 mins Attributes: Not Sent
23:24:26	DE		Mobilisation Turnout Methods Offered H242 : [W] [M] V
23:24:26	DE	H242	Officer In Charge changed from to S.41
23:24:26	DE	H242	Riders changed from 0 to 4
23:24:26	DE	H242	Status changed from 1 - At Station to R - Committed To Incident
23:24:26	DE	H242	Assigned to Incident (Inc No. -01012023)
23:24:26	DE	H242	Role changed from PUMPING APPLIANCE,LONDON PUMPING APPLIANCE to P
23:24:26	DE		Mobilisation DE Turnout H242 (W),H242 (M) to (Inc No. -01012023)
23:24:26	DE	H24	Mobilisation Relief - Relief
			Incident Number: (Inc No. -01012023) Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: F Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Type: 6PF Incident Type: A1F Incident Details: S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - START Group - Resources Being Assigned From This Location: Resource Call Sign: H242 Resource Attribute Codes: AS RELIEF NOW END Group - Resources Being Assigned From This Location Incident Address: , No. OLD KENT ROAD,LONDON,SE1 5LU Incident Resource Mobilisation Notes: H242 FOR ONE PUMP RELIEF AT 00:00 WITH LFF IN CHARGE Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: E232 Resource Call Sign: F121 Resource Call Sign: F63 Resource Call Sign: F110 Resource Call Sign: E1

			Resource Call Sign: F63 Resource Call Sign: BC02 Resource Call Sign: SA3 Resource Call Sign: H26S Resource Call Sign: PR4 END Group - Assigned Resources
23:24:26	DE		Mobilisation Required response not despatched 2/SUB OR STN OFFICER, 1/135 LADDER, 4/PUMPING APPLIANCE, 2/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
23:24:26	DE		Mobilisation Required response not despatched 2/SUB OR STN OFFICER, 1/135 LADDER, 4/PUMPING APPLIANCE, 2/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
23:24:26	DE	H242	Relief Sent - H242 (Inc No. -01012023)
23:24:26	DE		User Comment s.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** -
23:24:26	SYS		Turning out with message - H242 FOR ONE PUMP RELIEF AT 00:00 WITH LFF IN CHARGE
23:24:31	SYS		Incident turnout to H24 for H242 crew acknowledgement received [21665]
23:25:31	SYS		Incident turnout to H242 for H242 completed [21669]
23:25:32	SYS	H242	Incident turnout to H242 for H242 no crew acknowledgement received [21669]
23:46:37	CB		Action Prompt H242 (H24) not booked mobile to incident displayed to All
23:47:11	SYS	H242	000524-01012023 identified as a repeat of this incident
23:47:11	SYS	H242	Status changed from R - Committed To Incident to 2 - Proceeding to incident
23:59:22	SYS	H242	Officer In Charge changed from 46749D SUBO to -
02/01/2023-			Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
00:07:41	JW		Informative H242 - SUBO S.40 - ONE PUMP RELIEF NOW IMPLEMENTED AT SCENE OF S.41 SIX PUMP FIRE - H242 NOW ICP
00:07:44	JW		Service Request Service Request Completed: H242 - SUBO S.40 - ONE PUMP RELIEF NOW IMPLEMENTED AT SCENE OF S.41 SIX PUMP FIRE - H242 NOW ICP
00:09:13	JW	E232	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
00:09:13	JW	E232	Clear from Incident (Inc No. -01012023)
00:55:22	JW		Service Request Service Request Created: H242 - THAMES WATER IN ATTENDANCE ATTEMPTING TO ISOLATE WATER SUPPLY

00:55:25	JW		Service Request Service Request Completed: H242 - THAMES WATER IN ATTENDANCE ATTEMPTING TO ISOLATE WATER SUPPLY
01:14:29	JW		Informative SUP/REL - H242 - SUBO S.40 - SCENE OF SIX PUMP S.41 FIRE - ONE 22MM COLD WATER PIPE NOW ISOLATED BY THAMES WATER - NO FURTHER RELIEFS REQUIRED UNTIL FIT DAY DUTY RETURN - SCENE SECURITY AND DUTY OF CARE LEFT WITH MET POLICE - TMO
01:14:45	CB		Service Request Service Request InProgress: SUP/REL - H242 - SUBO S.40 - SCENE OF SIX PUMP S.41 FIRE - ONE 22MM COLD WATER PIPE NOW ISOLATED BY THAMES WATER - NO FURTHER RELIEFS REQUIRED UNTIL FIT DAY DUTY RETURN - SCENE SECURITY AND DUTY OF CARE LEFT WITH MET POLICE - TMO
01:15:47	SYS	H242	Status changed from 3 - In attendance at an incident to 6 - Immediately available by radio
01:15:47	SYS	H242	Clear from Incident Inc No. -01012023
01:15:47	SYS	H242	Current Station changed from H24 to E35
03:06:14	CB		Status changed from S - Stop to F - Finished
10:23:17	MPE	OK14	Relief Added - OK14 (Inc No. -01012023) Immediate: False Relief Time: 02/01/2023 12:23:00 Reserve: 30 mins
10:23:22	MPE	OK16	Relief Added - OK16 (Inc No. -01012023) Immediate: False Relief Time: 02/01/2023 12:23:00 Reserve: 30 mins
10:23:42	MPE		Relief general text changed to - OK14 AND OK16 RE-ATTENDING INCIDENT FOR FURTHER ONGOING FI
10:23:45	MPE		Mobilisation MPE Turnout OK14 (F),OK16 (F) to Inc No. -01012023
10:23:45	MPE	F90	Mobilisation Relief - Relief
			Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: F Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Type: 6PF Incident Type: A1F Incident Details: S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - START Group - Resources Being Assigned From This Location: Resource Call Sign: OK14 Resource Attribute Codes: AS RELIEF AT 12:23 Resource Call Sign: OK16 Resource Attribute Codes: AS RELIEF AT 12:23 END Group - Resources Being Assigned From This Location Incident Address: , No.

			OLD KENT ROAD,LONDON,SE1 5LU Incident Resource Mobilisation Notes: OK14 AND OK16 RE-ATTENDING INCIDENT FOR FURTHER ONGOING FI Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40
			START Group - Resources Being Assigned From Other Location: END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: F121 Resource Call Sign: F63 Resource Call Sign: F110 Resource Call Sign: E1 Resource Call Sign: F63 Resource Call Sign: BC02 Resource Call Sign: SA3 Resource Call Sign: H26S Resource Call Sign: PR4 END Group - Assigned Resources
10:23:45	MPE		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
10:23:45	MPE		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
10:23:45	MPE	OK14	Relief Sent - OK14 (Inc No. -01012023)
10:23:45	MPE	OK16	Relief Sent - OK16 (Inc No. -01012023)
10:23:45	MPE		User Comment S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** -
			Turning out with message - OK14 AND OK16 RE-ATTENDING INCIDENT FOR FURTHER ONGOING FI
10:23:45	SYS		Incident turnout to F90 for OK14,OK16 crew acknowledgement received [23034]
10:24:26	MPE		Mobilisation Turnout Methods Offered OK16 : [W] [M] V
10:24:26	MPE	OK16	Status changed from P - Available by pager to R - Committed To Incident
10:24:26	MPE	OK16	Assigned to Incident (Inc No. -01012023)
10:24:26	MPE		Mobilisation MPE Turnout OK16 (W),OK16 (M) to (Inc No. -01012023)
10:24:26	MPE	F90	Mobilisation Make Up - Makeup

			Incident Number: Inc No. -01012023
			Incident Call Date/Time: 01/01/2023 16:55:30
			Incident Type: F
			Incident Type: PR
			Incident Type: 4PF
			Incident Type: FSG
			Incident Type: 6PF
			Incident Type: A1F
			Incident Details: S.41 SIX PUMP FIRE FIRE
			FSG CALL IN PROGRESS - TL REQUESTED
			FROM SCENE
			* * TL TO APPROACH FROM DIRECTION OF
			ELEPHANT AND CASTLE** -
			Incident Address: No.
			OLD KENT ROAD,LONDON,SE1 5LU
			START Group - Resources Being Assigned
			From This Location:
			Resource Call Sign: OK16
			Resource Attribute Codes: FIU
			END Group - Resources Being Assigned From
			This Location
			Incident Map Book Reference: 7J/231
			Incident Station Ground: E35
			S.40
			START Group - Resources Being Assigned
			From Other Location:
			END Group - Resources Being Assigned From
			Other Location
			START Group - Assigned Resources:
			Resource Call Sign: F121
			Resource Call Sign: F63
			Resource Call Sign: F110
			Resource Call Sign: E1
			Resource Call Sign: F63
			Resource Call Sign: BC02
			Resource Call Sign: SA3
			Resource Call Sign: H26S
			Resource Call Sign: PR4
			Resource Call Sign: OK14
			END Group - Assigned Resources
			Mobilisation
			Required response not despatched 3/SUB OR
			STN OFFICER, 1/135 LADDER, 6/PUMPING
			APPLIANCE, 2/LONDON PUMPING APPLIANCE,
			1/FIRE INVESTIGATION UNIT, 2/COMMAND
			UNIT, 1/STATION COMMANDER, 1/FSG CU,
			1/SUB OR STN OFFICER (FSG), 1/PRESS
			LIAISON, 1/TURNTABLE LADDER, 1/AERIAL
			SUPPORT PUMP
10:24:26	MPE		Mobilisation
			Required response not despatched 3/SUB OR
			STN OFFICER, 1/135 LADDER, 6/PUMPING
			APPLIANCE, 2/LONDON PUMPING APPLIANCE,
			1/FIRE INVESTIGATION UNIT, 2/COMMAND
			UNIT, 1/STATION COMMANDER, 1/FSG CU,
			1/SUB OR STN OFFICER (FSG), 1/PRESS
			LIAISON, 1/TURNTABLE LADDER, 1/AERIAL
			SUPPORT PUMP
10:24:26	MPE		Mobilisation
			Required response not despatched 3/SUB OR
			STN OFFICER, 1/135 LADDER, 6/PUMPING
			APPLIANCE, 2/LONDON PUMPING APPLIANCE,
			1/FIRE INVESTIGATION UNIT, 2/COMMAND
			UNIT, 1/STATION COMMANDER, 1/FSG CU,
			1/SUB OR STN OFFICER (FSG), 1/PRESS
			LIAISON, 1/TURNTABLE LADDER, 1/AERIAL
			SUPPORT PUMP
10:24:28	SYS		Incident turnout to F90 for OK16 completed
			[23036]
10:24:36	MPE		Mobilisation Turnout Methods Offered
			OK14 : [W] [M] V
10:24:36	MPE	OK14	Status changed from P - Available by pager to R
			- Committed To Incident

10:24:36	MPE	OK14	Assigned to Incident Inc No. -01012023
10:24:36	MPE		Mobilisation MPE
10:24:36	MPE	F90	Turnout OK14 (W),OK14 (M) to Inc No. -01012023
			Mobilisation
			Make Up - Makeup
			Incident Number: Inc No. -01012023
			Incident Call Date/Time: 01/01/2023 16:55:30
			Incident Type: F
			Incident Type: PR
			Incident Type: 4PF
			Incident Type: FSG
			Incident Type: 6PF
			Incident Type: A1F
			Incident Details: S.41 SIX PUMP FIRE FIRE
			FSG CALL IN PROGRESS - TL REQUESTED
			FROM SCENE
			* * TL TO APPROACH FROM DIRECTION OF
			ELEPHANT AND CASTLE** -
			Incident Address: No.
			OLD KENT ROAD,LONDON,SE1 5LU
			START Group - Resources Being Assigned
			From This Location:
			Resource Call Sign: OK14
			Resource Attribute Codes: FIU
			END Group - Resources Being Assigned From
			This Location
			Incident Map Book Reference: 7J/231
			Incident Station Ground: E35
			S.40
			START Group - Resources Being Assigned
			From Other Location:
			END Group - Resources Being Assigned From
			Other Location
			START Group - Assigned Resources:
			Resource Call Sign: OK16
			Resource Call Sign: F121
			Resource Call Sign: F63
			Resource Call Sign: F110
			Resource Call Sign: E1
			Resource Call Sign: F63
			Resource Call Sign: BC02
			Resource Call Sign: SA3
			Resource Call Sign: H26S
			Resource Call Sign: PR4
			END Group - Assigned Resources
10:24:37	MPE		Mobilisation
			Required response not despatched 3/SUB OR
			STN OFFICER, 1/135 LADDER, 6/PUMPING
			APPLIANCE, 2/LONDON PUMPING APPLIANCE,
			2/COMMAND UNIT, 1/STATION COMMANDER,
			1/FSG CU, 1/SUB OR STN OFFICER (FSG),
			1/PRESS LIAISON, 1/TURNTABLE LADDER,
			1/AERIAL SUPPORT PUMP
10:24:37	MPE		Mobilisation
			Required response not despatched 3/SUB OR
			STN OFFICER, 1/135 LADDER, 6/PUMPING
			APPLIANCE, 2/LONDON PUMPING APPLIANCE,
			2/COMMAND UNIT, 1/STATION COMMANDER,
			1/FSG CU, 1/SUB OR STN OFFICER (FSG),
			1/PRESS LIAISON, 1/TURNTABLE LADDER,
			1/AERIAL SUPPORT PUMP
10:24:37	SYS		Incident turnout to F90 for OK16 crew
			acknowledgement received [23036]

10:24:37	SYS		Incident turnout to F90 for OK14 completed [23041]
10:24:40	SYS		Incident turnout to F90 for OK14 crew acknowledgement received [23041]
10:25:04	MPE	OK14	Status changed from R - Committed To Incident to 2 - Proceeding to incident
10:25:09	MPE	OK16	Status changed from R - Committed To Incident to 2 - Proceeding to incident
10:25:26	SYS		Incident turnout to OK16 for OK16 failed [23039]
10:25:26	MPE	OK16	Remarks changed from RTB 05:04 2/1 to
10:25:42	SYS		Incident turnout to OK14 for OK14 no crew acknowledgement received [23044]
10:25:48	SYS		Incident turnout to OK14 for OK14 failed [23044]
10:30:15	EI2		Mobilisation Turnout Methods Offered SA4 : [P] V
10:30:15	EI2	SA4	Status changed from P - Available by Paging to R - Committed
10:30:15	EI2	SA4	Role set to SCIENTIFIC ADVISER
10:30:15	EI2	SA4	Assigned to Incident Inc No. -01012023
10:30:15	EI2		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
10:30:15	EI2		Mobilisation EI2 Turnout SA4 (P) to Inc No. -01012023
10:30:15	EI2		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
10:30:16	SYS		Incident turnout to SA4 for SA4 completed [23059]
10:31:25	EI2		Agency SA4 MOBILISED TO INCIDENT ON REQUEST OF FIRE INVESTIGATION
10:37:23	ER	SA4	Status changed from R - Committed to 2 - Proceeding to incident
11:10:47	ER	SA4	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
11:22:34	AS1		Service Request Service Request Completed: SUP/REL - H242 - SUBO S.40 - SCENE OF SIX PUMP S.41 FIRE - ONE 22MM COLD WATER PIPE NOW ISOLATED BY THAMES WATER - NO FURTHER RELIEFS REQUIRED UNTIL FIT DAY DUTY RETURN - SCENE SECURITY AND DUTY OF CARE LEFT WITH MET POLICE - TMO
11:24:35	KH	OK14	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
11:24:38	KH	OK16	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
12:07:53	AW		Make Up AW - IUP - OK16 STNO S.40 - REQUEST ONE PUMP TO ASSIST WITH UNSAFE MASONRY AT

			FRONT OF PROPERTY ABOVE WHERE FIT ARE WORKING
12:09:58	AW		Mobilisation Turnout Methods Offered
12:09:58	AW	E351	E351 : [W] [M] V
12:09:58	AW	E351	Officer In Charge changed from to 50956W SUBO
12:09:58	AW	E351	Riders changed from 0 to 5
12:09:58	AW	E351	Status changed from 1 - At Station to R - Committed To Incident
12:09:58	AW	E351	Assigned to Incident Inc No. -01012023
12:09:58	AW	E351	Role changed from PUMPING APPLIANCE,LONDON PUMPING APPLIANCE to PL
12:09:58	AW		Mobilisation AW
12:09:58	AW	E35	Turnout E351 (W),E351 (M) to Inc No. -01012023
12:09:58	AW	E35	Mobilisation
			Make Up - Makeup
			Incident Number: Inc No. -01012023
			Incident Call Date/Time: 01/01/2023 16:55:30
			Incident Type: F
			Incident Type: PR
			Incident Type: 4PF
			Incident Type: FSG
			Incident Type: 6PF
			Incident Type: A1F
			Incident Details: S.41 SIX PUMP FIRE FIRE
			FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE
			* * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** -
			Incident Address: , No.
			OLD KENT ROAD,LONDON,SE1 5LU
			START Group - Resources Being Assigned From This Location:
			Resource Call Sign: E351
			Resource Attribute Codes: PL
			END Group - Resources Being Assigned From This Location
			Incident Map Book Reference: 7J/231
			Incident Station Ground: E35
			S.40
			START Group - Resources Being Assigned From Other Location:
			END Group - Resources Being Assigned From Other Location
			START Group - Assigned Resources:
			Resource Call Sign: OK16
			Resource Call Sign: OK14
			Resource Call Sign: F121
			Resource Call Sign: F63
			Resource Call Sign: F110
			Resource Call Sign: E1
			Resource Call Sign: F63
			Resource Call Sign: BC02
			Resource Call Sign: SA3
			Resource Call Sign: H26S
			Resource Call Sign: PR4
			Resource Call Sign: SA4
			END Group - Assigned Resources
			Incident Resource Mobilisation Notes:
			REQUESTED TO ASSIST WITH UNSAFE MASONRY ABOVE FIT WORKING AREA

12:09:58	AW		Mobilisation Required response not despatched 2/SUB OR STN OFFICER, 5/PUMPING APPLIANCE, 1/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/PRESS LIAISON, 1/TURNTABLE LADDER
12:09:58	AW		Mobilisation Required response not despatched 2/SUB OR STN OFFICER, 5/PUMPING APPLIANCE, 1/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/PRESS LIAISON, 1/TURNTABLE LADDER
12:09:58	AW		User Comment S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** -
12:09:58	SYS		Turning out with message - REQUESTED TO ASSIST WITH UNSAFE MASONRY ABOVE FIT WORKING AREA Incident turnout to E35 for E351 crew acknowledgement received [23313]
12:10:00	SYS		Incident turnout to E351 for E351 completed [23317]
12:10:22	AW		Service Request Service Request Completed: AW - IUP - OK16 STNO S.40 - REQUEST ONE PUMP TO ASSIST WITH UNSAFE MASONRY AT FRONT OF PROPERTY ABOVE WHERE FIT ARE WORKING
12:11:00	SYS		Incident turnout to E351 for E351 crew acknowledgement received [23317]
12:11:01	SYS	E351	Status changed from R - Committed To Incident to 2 - Proceeding to incident
12:11:01	SYS	E351	Officer In Charge changed from 50956W SUBO to -
12:11:24	SYS	E351	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
12:41:16	SYS	E351	Status changed from 3 - In attendance at an incident to 6 - Immediately available by radio
12:41:16	SYS	E351	Clear from Incident Inc No. -01012023
13:24:12	PJ1		Key UKPN REQUESTED URGENTLY TO ISOLATE SUPPLY REF CALL619350J
13:24:25	PJ1		OtherAgencyCallRef changed from TFL REF 311 TWA 31920995 / TWA NEW REFERENCE 31920998 to TFL REF 311 TWA 31920995 / TWA NEW REFERENCE 31920998 / UKPN REF CALL619350J
13:28:34	PJ1		Key FIT CALLED TO CHECK IF ANYTHING ON THE LOG FOR UKPN TO ISOLATE SUPPLY - NOTHING FOUND - UKPN REQUESTED - ETA WITHIN THE HOUR BUT SHOULD ALSO CALL BACK TO CONFIRM - FIT UPDATED
17:02:28	KH	OK14	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
17:02:28	KH	OK14	Clear from Incident Inc No. -01012023
17:03:14	KH	OK16	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
17:03:14	KH	OK16	Clear from Incident Inc No. -01012023

17:16:54	MPE	SA4	Status changed from 3 - In attendance at an incident to P - Available by Paging
17:16:54	MPE	SA4	Clear from Incident Inc No. -01012023
17:21:47	MPE		Details changed from S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * TL TO APPROACH FROM DIRECTION OF ELEPHANT AND CASTLE** - to S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * INCIDENT TO BE LEFT OPEN AS SA4 WILL BE RE-ATTENDING WITH FIT ON 03/01/23 * *
03/01/2023-			
09:42:29	DS		Mobilisation Turnout Methods Offered OK16 : [W] [M] V
09:42:29	DS	OK16	Status changed from P - Available by pager to R - Committed To Incident
09:42:29	DS	OK16	Assigned to Incident Inc No. -01012023
09:42:29	DS		Mobilisation DS Turnout OK16 (W),OK16 (M) to Inc No. -01012023
09:42:29	DS	F90	Mobilisation Make Up - Makeup
Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: F Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Type: 6PF Incident Type: A1F Incident Details: S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * INCIDENT TO BE LEFT OPEN AS SA4 WILL BE RE-ATTENDING WITH FIT ON 03/01/23 * * Incident Address: No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: OK16 Resource Attribute Codes: FIU END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: F121 Resource Call Sign: F63 Resource Call Sign: F110 Resource Call Sign: E1 Resource Call Sign: F63 Resource Call Sign: BC02 Resource Call Sign: SA3 Resource Call Sign: H26S Resource Call Sign: PR4 END Group - Assigned Resources			

09:42:29	DS		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 1/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
09:42:29	DS		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 1/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
09:42:30	SYS		Incident turnout to F90 for OK16 completed [27655]
09:42:36	SYS		Incident turnout to F90 for OK16 crew acknowledgement received [27655]
09:42:42	DS		Mobilisation Turnout Methods Offered OK15 : [W] [M] V
09:42:42	DS	OK15	Status changed from P - Available by pager to R - Committed To Incident
09:42:42	DS	OK15	Assigned to Incident Inc No. -01012023
09:42:42	DS	OK15	Role changed from FIRE INVESTIGATION UNIT to FIU
09:42:42	DS		Mobilisation DS
09:42:42	DS	F90	Turnout OK15 (W),OK15 (M) to Inc No. -01012023
09:42:42	DS		Mobilisation Make Up - Makeup Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: F Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Type: 6PF Incident Type: A1F Incident Details: S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * INCIDENT TO BE LEFT OPEN AS SA4 WILL BE RE-ATTENDING WITH FIT ON 03/01/23 * * Incident Address: No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: OK15 Resource Attribute Codes: FIU END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: OK16

			Resource Call Sign: F121 Resource Call Sign: F63 Resource Call Sign: F110 Resource Call Sign: E1 Resource Call Sign: F63 Resource Call Sign: BC02 Resource Call Sign: SA3 Resource Call Sign: H26S Resource Call Sign: PR4 END Group - Assigned Resources
09:42:42	DS		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
09:42:42	DS		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
09:42:43	SYS		Incident turnout to F90 for OK15 completed [27660]
09:42:57	SYS		Incident turnout to F90 for OK15 crew acknowledgement received [27660]
09:43:34	SYS		Incident turnout to OK16 for OK16 no crew acknowledgement received [27658]
09:43:37	SYS	OK16	Action Prompt OK16 (F90) not booked mobile to incident displayed to All
09:43:39	SYS	OK16	Action Prompt OK16 (F90) not alerted displayed to All
09:43:39	SYS		Incident turnout to OK16 for OK16 failed [27658]
09:43:47	SYS	OK15	Action Prompt OK15 (F90) not booked mobile to incident displayed to All
09:43:47	SYS		Incident turnout to OK15 for OK15 no crew acknowledgement received [27663]
09:44:16	SYS	OK15	Action Prompt OK15 (F90) not alerted displayed to All
09:44:16	SYS		Incident turnout to OK15 for OK15 failed [27663]
10:08:07	CMW	OK15	Status changed from R - Committed To Incident to 3 - In attendance at an incident
10:14:10	CMW	OK16	Status changed from R - Committed To Incident to 3 - In attendance at an incident
10:41:57	MT		Mobilisation Turnout Methods Offered SA4 : [P] V
10:41:57	MT	SA4	Status changed from P - Available by Paging to R - Committed
10:41:57	MT	SA4	Role set to SA
10:41:57	MT	SA4	Assigned to Incident Inc No. -01012023
10:41:57	MT		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP

10:41:57	MT		Mobilisation MT Turnout SA4 (P) to Inc No. -01012023
10:41:57	MT		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
10:41:58	SYS		Incident turnout to SA4 for SA4 completed [27922]
10:42:09	MT	SA4	Status changed from R - Committed to 3 - In attendance at an incident
10:42:39	MT		Key SA4 ATTENDING TO ASSIST FIRE INVESTIGATION
11:31:52	DC		Mobilisation Turnout Methods Offered E351 : [W] [M] V
11:31:52	DC	E351	Status changed from 7 - Not immediately available to R - Committed To Incident
11:31:52	DC	E351	Assigned to Incident Inc No. -01012023
11:31:52	DC	E351	Role changed from PUMPING APPLIANCE,LONDON PUMPING APPLIANCE to PL
11:31:52	DC		Mobilisation DC Turnout E351 (W),E351 (M) to Inc No. -01012023
11:31:52	DC	E35	Mobilisation Make Up - Makeup
Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: F Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Type: 6PF Incident Type: A1F Incident Details: S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * INCIDENT TO BE LEFT OPEN AS SA4 WILL BE RE-ATTENDING WITH FIT ON 03/01/23 * * Incident Address: , No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: E351 Resource Attribute Codes: PL END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: OK16 Resource Call Sign: OK15 Resource Call Sign: F121 Resource Call Sign: F63			

			Resource Call Sign: F110 Resource Call Sign: E1 Resource Call Sign: F63 Resource Call Sign: BC02 Resource Call Sign: SA3 Resource Call Sign: H26S Resource Call Sign: PR4 Resource Call Sign: SA4 END Group - Assigned Resources Incident Resource Mobilisation Notes: E351 FOR LIGHTING TO ASSIST FIU
11:31:52	DC		Mobilisation Required response not despatched 2/SUB OR STN OFFICER, 5/PUMPING APPLIANCE, 1/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/PRESS LIAISON, 1/TURNTABLE LADDER
11:31:52	DC		Mobilisation Required response not despatched 2/SUB OR STN OFFICER, 5/PUMPING APPLIANCE, 1/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/PRESS LIAISON, 1/TURNTABLE LADDER
11:31:52	DC		User Comment s.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * INCIDENT TO BE LEFT OPEN AS SA4 WILL BE RE-ATTENDING WITH FIT ON 03/01/23 * *
11:31:52	SYS		Turning out with message - E351 FOR LIGHTING TO ASSIST FIU Incident turnout to E35 for E351 crew acknowledgement received [28034]
11:31:55	SYS		Incident turnout to E351 for E351 completed [28038]
11:32:01	DC		Agency E351 FOR LIGHTING TO ASSIST FIU
11:32:57	SYS	E351	Action Prompt E351 (E35) not booked mobile to incident displayed to All
11:32:58	SYS		Incident turnout to E351 for E351 no crew acknowledgement received [28038]
11:33:24	SYS	E351	Status changed from R - Committed To Incident to 2 - Proceeding to incident
11:33:24	SYS	E351	Officer In Charge changed from s.40 SUBO to -
11:34:15	DC		Service Request Service Request Created: RT5 - OK16 - E351 ORDERED FOR LIGHTING
11:35:17	LF		Service Request Service Request InProgress: RT5 - OK16 - E351 ORDERED FOR LIGHTING
11:42:07	SYS	E351	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
11:47:36	SYS	E351	Status changed from 3 - In attendance at an incident to 6 - Immediately available by radio
11:47:36	SYS	E351	Clear from Incident Inc No. -01012023
11:55:42	CMW		Service Request Service Request Updated from RT5 - OK16 - E351 ORDERED FOR LIGHTING, to CMW RT5 - OK16 - E351 ORDERED FOR LIGHTING
12:15:01	CMW		Service Request Service Request Completed: CMW RT5 - OK16 - E351 ORDERED FOR LIGHTING

14:08:03	DAS		Mobilisation Turnout Methods Offered OK13 : [W] [M] V
14:08:03	DAS	OK13	Status changed from P - Available by pager to R - Committed To Incident
14:08:03	DAS	OK13	Assigned to Incident Inc No. -01012023
14:08:03	DAS	OK13	Role changed from FIRE INVESTIGATION UNIT,FIU to FIU
14:08:03	DAS		Mobilisation DAS Turnout OK13 (W),OK13 (M) to Inc No. -01012023
14:08:03	DAS	F90	Mobilisation Make Up - Makeup
			Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Type: F Incident Type: PR Incident Type: 4PF Incident Type: FSG Incident Type: 6PF Incident Type: A1F Incident Details: S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * INCIDENT TO BE LEFT OPEN AS SA4 WILL BE RE-ATTENDING WITH FIT ON 03/01/23 * * Incident Address: No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: OK13 Resource Attribute Codes: FIU END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: END Group - Resources Being Assigned From Other Location START Group - Assigned Resources: Resource Call Sign: OK16 Resource Call Sign: OK15 Resource Call Sign: F121 Resource Call Sign: F63 Resource Call Sign: F110 Resource Call Sign: E1 Resource Call Sign: F63 Resource Call Sign: BC02 Resource Call Sign: SA3 Resource Call Sign: H26S Resource Call Sign: PR4 Resource Call Sign: SA4 END Group - Assigned Resources
14:08:03	DAS		Mobilisation Required response not despatched 3/SUB OR STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
14:08:03	DAS		Mobilisation Required response not despatched 3/SUB OR

			STN OFFICER, 1/135 LADDER, 6/PUMPING APPLIANCE, 2/LONDON PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/PRESS LIAISON, 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP
14:08:03	SYS		Incident turnout to F90 for OK13 crew acknowledgement received [28623]
14:08:07	DAS	OK13	Status changed from R - Committed To Incident to 3 - In attendance at an incident
14:09:08	SYS		Incident turnout to OK13 for OK13 failed [28626]
16:19:03	SR	SA4	Status changed from 3 - In attendance at an incident to P - Available by Paging
16:19:03	SR	SA4	Clear from Incident Inc No. -01012023
16:20:31	CMW	OK15	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
16:20:31	CMW	OK15	Clear from Incident Inc No. -01012023
16:52:44	LF	OK16	Status changed from 3 - In attendance at an incident to 7 - Not immediately available
16:52:44	LF	OK16	Clear from Incident Inc No. -01012023
17:33:50	BB	OK13	Status changed from 3 - In attendance at an incident to P - Available by pager
17:33:50	BB	OK13	Clear from Incident Inc No. -01012023
19:43:44	MT		Incident Closed
04/01/2023-			
07:48:50	PJ1		Incident reopened
07:48:50	SYS		R/C set to 35
07:48:50	SYS		Relief general text changed to - OK14 AND OK16 RE-ATTENDING INCIDENT FOR FURTHER ONGOING FI
07:48:51	SYS		Tag 30 added
07:48:51	SYS		Tag 4PF added
07:48:51	SYS		Tag 6PF added
07:48:51	SYS		Tag A1 added
07:48:51	SYS		Tag A1_DEFAULT added
07:48:51	SYS		Tag A1F added
07:48:51	SYS		Tag FSG added
07:48:51	SYS		Tag PR added
07:48:51	SYS		Tag SM1 added
07:48:52	SYS		Action
			Action Plan 2755 Activated
07:48:52	SYS		Action
			Action Plan 2710 Activated
07:48:52	SYS		Action
			Action Plan 2670 Activated
07:49:02	PJ1		Mobilisation Turnout Methods Offered
07:49:02	PJ1	OK13	OK13 : [W] [M] V
07:49:02	PJ1	OK13	Status changed from P - Available by pager to R - Committed To Incident
07:49:02	PJ1	OK13	Assigned to Incident Inc No. -01012023
07:49:02	PJ1	OK13	Role changed from FIRE INVESTIGATION UNIT,FIU to FIU
07:49:02	PJ1		Mobilisation PJ1
07:49:02	PJ1	F90	Turnout OK13 (W),OK13 (M) to Inc No. -01012023
07:49:02	PJ1		Mobilisation
07:49:02	PJ1		Initial - Turnout

			Incident Number: Inc No. -01012023 Incident Call Date/Time: 01/01/2023 16:55:30 Incident Creation Date/Time: 01/01/2023 16:56:24 Incident Type: F Incident Type: 4PF Incident Type: 6PF Incident Type: A1F Incident Type: FSG Incident Type: PR Incident Details: S.41 SIX PUMP FIRE FIRE FSG CALL IN PROGRESS - TL REQUESTED FROM SCENE * * INCIDENT TO BE LEFT OPEN AS SA4 WILL BE RE-ATTENDING WITH FIT ON 03/01/23 * * Incident Address: No. OLD KENT ROAD,LONDON,SE1 5LU START Group - Resources Being Assigned From This Location: Resource Call Sign: OK13 Resource Attribute Codes: FIU END Group - Resources Being Assigned From This Location Incident Map Book Reference: 7J/231 Incident Station Ground: E35 S.40 START Group - Resources Being Assigned From Other Location: END Group - Resources Being Assigned From Other Location Caller Phone Number: Caller No. Incident SECH Information: OtherAgencyCallRef - TFL REF 311 TWA 31920995 / TWA NEW REFERENCE 31920998 / UKPN REF CALL619350J Mobilisation Required response not despatched 1/135 LADDER, 6/PUMPING APPLIANCE, 1/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 3/SUB OR STN OFFICER, 1/PRESS LIAISON, 2/LONDON PUMPING APPLIANCE, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP Mobilisation Required response not despatched 1/135 LADDER, 6/PUMPING APPLIANCE, 1/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 3/SUB OR STN OFFICER, 1/PRESS LIAISON, 2/LONDON PUMPING APPLIANCE, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP Incident turnout to F90 for OK13 crew acknowledgement received [31614] Agency FIRE INVESTIGATION CALLED UP TO ASSIGN OK13 TO INCIDENT Incident turnout to OK13 for OK13 no crew acknowledgement received [31617] Action Prompt OK13 (F90) not booked mobile to incident displayed to All
07:49:02	PJ1		
07:49:02	PJ1		
07:49:02	SYS		
07:49:28	PJ1		
07:50:07	SYS		
07:50:09	SYS	OK13	

07:50:13	SYS	OK13	Action Prompt OK13 (F90) not alerted displayed to All
07:50:13	SYS		Incident turnout to OK13 for OK13 failed [31617]
07:50:37	PJ1		Action
			All outstanding actions cancelled
08:07:57	SF1		Informative
			STNO MAY - REQUEST 2 LIGHTING UNITS AND TRIPODS TO BE DROPPED OFF AT SCENE
08:16:52	SF1		Key
			BABCOCKS - LIGHTING UNITS ORDERED REF FB2301040001 ETA WITHIN 2 HOURS
08:17:22	SF1	OK13	Make Up
			Make BULK FOAM UNIT 1 Requested
08:26:53	JM	OK13	Status changed from R - Committed To Incident to 2 - Proceeding to incident
08:27:51	JM	OK13	Make Up
			Make BULK FOAM UNIT 2 Requested
08:28:15	JM	OK13	Make Up
			Make BULK FOAM UNIT 1 Requested
08:39:05	JM		Mobilisation Turnout Methods Offered
			SA4 : [P] V
08:39:05	JM	SA4	Status changed from P - Available by Paging to R - Committed
08:39:05	JM	SA4	Role set to SA
08:39:05	JM	SA4	Assigned to Incident Inc No. -01012023
08:39:05	JM		Mobilisation
			Required response not despatched 1/135 LADDER, 6/PUMPING APPLIANCE, 1/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 3/SUB OR STN OFFICER, 1/PRESS LIAISON, 2/LONDON PUMPING APPLIANCE, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP, 1/BULK FOAM UNIT
08:39:05	JM		Mobilisation JM
			Turnout SA4 (P) to Inc No. -01012023
08:39:05	JM		Mobilisation
			Required response not despatched 1/135 LADDER, 6/PUMPING APPLIANCE, 1/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 3/SUB OR STN OFFICER, 1/PRESS LIAISON, 2/LONDON PUMPING APPLIANCE, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP, 1/BULK FOAM UNIT
08:39:06	SYS		Incident turnout to SA4 for SA4 completed [31757]
08:39:13	JM	SA4	Status changed from R - Committed to 2 - Proceeding to incident
08:39:19	JM	SA4	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
08:40:11	RC1		Mobilisation Turnout Methods Offered
			E351 : [W] [M] V
08:40:11	RC1	E351	Officer In Charge changed from to 50956W SUBO
08:40:11	RC1	E351	Riders changed from 0 to 5
08:40:11	RC1	E351	Status changed from 1 - At Station to R - Committed To Incident
08:40:11	RC1	E351	Assigned to Incident Inc No. -01012023
08:40:11	RC1	E351	Role changed from PUMPING APPLIANCE,135 LADDER to PL

08:40:11	RC1		Mobilisation RC1 Turnout E351 (W),E351 (M) to Inc No. -01012023
08:40:11	RC1	E35	Mobilisation Make Up - Makeup
08:40:11	RC1		Mobilisation Required response not despatched 5/PUMPING APPLIANCE, 1/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 2/SUB OR STN OFFICER, 1/PRESS LIAISON, 1/LONDON PUMPING APPLIANCE, 1/FSG CU, 1/TURNTABLE LADDER, 1/BULK FOAM UNIT
08:40:11	RC1		Mobilisation Required response not despatched 5/PUMPING APPLIANCE, 1/FIRE INVESTIGATION UNIT, 2/COMMAND UNIT, 1/STATION COMMANDER, 2/SUB OR STN OFFICER, 1/PRESS LIAISON, 1/LONDON PUMPING APPLIANCE, 1/FSG CU, 1/TURNTABLE LADDER, 1/BULK FOAM UNIT
08:40:12	SYS		Incident turnout to E35 for E351 completed [31759]
08:40:15	SYS		Incident turnout to E351 for E351 completed [31762]
08:40:20	SYS		Incident turnout to E35 for E351 crew acknowledgement received [31759]
08:41:16	SYS		Incident turnout to E351 for E351 no crew acknowledgement received [31762]
08:41:19	SYS	E351	Action Prompt E351 (E35) not booked mobile to incident displayed to All
08:41:35	RC1		Key BABCOCKS LIGHTING CANCELLED E351 MOBILISED WITH LIGHTING UNITS AND TRIPODS
08:42:27	SYS	E351	Status changed from R - Committed To Incident to 2 - Proceeding to incident
08:42:27	SYS	E351	Officer In Charge changed from 50956W SUBO to -
08:45:25	SYS	E351	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
08:48:42	SYS	E351	Status changed from 3 - In attendance at an incident to 6 - Immediately available by radio
08:48:42	SYS	E351	Clear from Incident Inc No. -01012023
12:14:09	HR1		Mobilisation Turnout Methods Offered OK15 : [W] [M] V
12:14:09	HR1	OK15	Status changed from P - Available by pager to R - Committed To Incident
12:14:09	HR1	OK15	Assigned to Incident Inc No. -01012023
12:14:09	HR1		Mobilisation HR1 Turnout OK15 (W),OK15 (M) to Inc No. -01012023
12:14:09	HR1	F90	Mobilisation Make Up - Makeup
12:14:09	HR1		Mobilisation Required response not despatched 1/135 LADDER, 6/PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 3/SUB OR STN OFFICER, 1/PRESS LIAISON, 2/LONDON PUMPING APPLIANCE, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP, 1/BULK FOAM UNIT
12:14:09	HR1		Mobilisation Required response not despatched 1/135

			LADDER, 6/PUMPING APPLIANCE, 2/COMMAND UNIT, 1/STATION COMMANDER, 3/SUB OR STN OFFICER, 1/PRESS LIAISON, 2/LONDON PUMPING APPLIANCE, 1/FSG CU, 1/SUB OR STN OFFICER (FSG), 1/TURNTABLE LADDER, 1/AERIAL SUPPORT PUMP, 1/BULK FOAM UNIT
12:14:09	SYS		Incident turnout to F90 for OK15 completed [32711]
12:14:37	HR1	OK15	Status changed from R - Committed To Incident to 2 - Proceeding to incident
12:15:14	SYS		Incident turnout to F90 for OK15 no crew acknowledgement received [32711]
12:15:14	SYS		Incident turnout to OK15 for OK15 no crew acknowledgement received [32714]
12:15:15	SYS		Incident turnout to OK15 for OK15 failed [32714]
12:37:26	SS	OK15	Status changed from 2 - Proceeding to incident to 3 - In attendance at an incident
17:10:12	JM	SA4	Status changed from 3 - In attendance at an incident to P - Available by Paging
17:10:12	JM	SA4	Clear from Incident Inc No. -01012023
18:04:37	HR1	OK15	Status changed from 3 - In attendance at an incident to P - Available by pager
18:04:37	HR1	OK15	Clear from Incident Inc No. -01012023
20:38:44	AW	OK13	User Comment
20:38:44	AW	OK13	.
20:38:44	AW	OK13	Status changed from 2 - Proceeding to incident to 0 - Not Available
20:38:44	AW	OK13	Clear from Incident Inc No. -01012023
21:01:26	HR1		Incident Closed

End of Log - Inc No.